			*			
ROTAX.		TECHNICAL NOTE No. 535-01	Page 1 of 4			
Subject	:	Flywheel on drive side.	:			
Models affected	:	Glider engines 535 series A and B, serial number V535/1407, 1408, 1428, 1429, 1485, 1497, 1499, 1532, 1552, 1553, 1554.				
Reason	:	In consequence of torsional vibration reso- nance in the operating range, the crankshaft could get overloaded.				
Compliance	:	Compliance is required by reaching of 10 engines hours or not later than June 30,1984.				
Instructions	:	 Remove magneto-flywheel from crankshaft, see repair procedure (pages 3 and 4), and check taper and wodruff key for damage. In case of no damage, remount magneto- flywheel. In the other case the engine must be repaired by Rotax. 				
		2) Remove drive pulley from and mount pulley with add as per drawing Skz. 2781	the crankshaft litional flywheel on page 2.			
Weight change	:	Weight increases by 0,85 kg (1,87 lbs).				
CG Position	:	Center of gravity must be ch	ecked.			
Note	:	In case of the Janus CM, the increases by 0,2 kg (0,44 lt	e tail load os).			
		The drawing shows the situat toothed belt of 65 mm width. belt dimensions, the flywhee accordingly.	tion of a HTD- For the other I has to be made			
		The material is available by manufacturer.	the aircraft			
		The work has to be performed person and has to be confirm aircraft logbook.	by a competent ed in the			
N						
D.U.C.	2-7	Approved b Bundesamt für Zivi	y lluftfahrt 840131 M			
Gunskirchen, 83	12	20	1			
BOMBARDIE	ER-I	ROTAX GMBH, A-4623 GUNSKIRCHE	N, AUSTRIA			

...

;

î.



	ROTAX.	TECHNICAL NOTE No. 535-01		Page 3 of
Repa	air instructineto flywheel	ion for disassembly and L	remounting	g of the
1) 1	Disassembly:	-	· .	
	I.1. Remove of <u>Tools:</u> S	cover washer (fig. 1) Socket wrench 13 mm		
	1.2. Bolt fly hexhead	wheel holder to magneto screws M8 x 16 (fig. 2)	flywheel	with 3
	Tools: I	Flywheel holder 876 080 Socket wrench 13 mm		
	1.3. Unscrew	hexagonal nut M22 x 1,5	(fig. 3)	
	Tools: S	Socket wrench 30 mm with (torque wrench)	(extension	1
	1.4. Fit prot holder a <u>Tools:</u> J	tection mushroom to cran and puller and remove ma Protection mushroom 876 Puller with flywheel bol	kshaft, mo gneto flyw 557 der and su	ount flywhee wheel (fig.
	Note: 1 Note: 1	Wrench 22 mm To facilitate removal, t neated carefully to 120°	the taper r	portion can
			Fig	. 1
				Construction of the last
	A STATE OF S	il (the second		
		To Toes		
•••				
	Contraction of the second seco	Cove	r washer	
	A CONSCIONANT OF THE OWNER OWNER OF THE OWNER	To cove	r washer	
		To Cove	r washer	
	A CONSCIENCE OF	To the state of th	r washer	
		Cove	r washer	

e'

