

Publication Index for ROTAX® Aircraft Engines

ATA System: 00-00-00 GENERAL NOTE

MANDATORY

1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods and prevailing legal regulations.

BRP-Powertrain GmbH & Co KG. cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

1.1) Applicability

All engines of type:

| Engine type | Serial number |
|---------------|-----------------------|
| 912 A | (Series / Pre-series) |
| 912 F | (Series / Pre-series) |
| 912 S | (Series / Pre-series) |
| 912 iSc Sport | (Series / Pre-series) |
| 914 F | (Series / Pre-series) |
| 505 | (Series / Pre-series) |
| 505 A | (Series / Pre-series) |
| 535 A | (Series / Pre-series) |
| 535 B | (Series / Pre-series) |
| 535 C | (Series / Pre-series) |

1.2) Concurrent ASB/SB/SI and SL

none

1.3) Reason

List of valid documentation in accordance with Part 21A.57 "Instruction for continued airworthiness".

1.4) Subject

Publication Index for ROTAX® Aircraft Engines.

SERVICE BULLETIN

1.5) Compliance

MANDATORY

For continued airworthiness keep the documentation to the latest valid revision level in accordance with the list attached in chapter 4 and the information on the ROTAX[®] AIRCRAFT ENGINES homepage.



Non-compliance with these instructions could result in engine damages, personal injuries or death!

1.6) Approval

The technical content of this document is approved under the authority of DOA ref. EASA.21J.048.

2) Material Information

none

3) Accomplishment / Instructions

Incorporation / exchange of relevant documentation.

3.1) Enquiries

The following table (list of effective documentation, issue 2016.06.20, page 1-18) includes all the valid documentation for the engine types described in section 1.1).

NOTE: Because of the multitude of documentation a continual updating of the tables is not possible. This Service Bulletin, however, will be updated/revised twice a year. The current documentation (current issue) or relevant revisions (replacement pages) are available at any ROTAX[®] authorized distributor or their independent Service Center in printed version or on the ROTAX[®] AIRCRAFT ENGINES homepage www.FLYROTAX.com (in subsection >Services >Technical Documentation) in electronic and current version.

Symbols used For meaning of the symbols used in this document, see chapter >Safety< in latest Operators Manual of the respective engine type.

Approval of translation to best knowledge and judgement-in any case the original text in English language and the metric units are authoritative.

Publication Index for ROTAX 2-stroke aircraft engines and all versions of ROTAX aircraft engines type 912 / 912 i / 914

ROTAX
AIRCRAFT ENGINES



| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|---|-------|----------|------------|--------|---|
| CD-447 | 447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 22 | 01.12.2015 | 899745 | Documentation CD-Rom ROTAX 912i, 912 and 914 (Series) and 2-stroke aircraft engines |
| CD-503 | 447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 22 | 01.12.2015 | 899745 | Documentation CD-Rom ROTAX 912i, 912 and 914 (Series) and 2-stroke aircraft engines |
| CD-582 | 447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 22 | 01.12.2015 | 899745 | Documentation CD-Rom ROTAX 912i, 912 and 914 (Series) and 2-stroke aircraft engines |
| CD-912 | 447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 22 | 01.12.2015 | 899745 | Documentation CD-Rom ROTAX 912i, 912 and 914 (Series) and 2-stroke aircraft engines |
| CD-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 22 | 01.12.2015 | 899745 | Documentation CD-Rom ROTAX 912i, 912 and 914 (Series) and 2-stroke aircraft engines |
| CD-914 | 447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 22 | 01.12.2015 | 899745 | Documentation CD-Rom ROTAX 912i, 912 and 914 (Series) and 2-stroke aircraft engines |
| DIV-2ST | 185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 642, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 24.08.2007 | | Customer Service Information Report |
| DIV-2ST | 185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 642, 912 A, 912 F, 912 iS, 912 iS Sport, 912 iSc Sport, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 3 | 0 | 19.05.2014 | 898602 | ROTAX Aircraft Engine Registration Card |
| DIV-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 3 | 20.01.2014 | | BRP Utility and Diagnostic Software B.U.D.S. Aircraft V2.4 |
| DIV-914 | 914 F, 914 UL | 0 | 0 | 01.01.2001 | | Monitoring-Program TLR 4.5a |
| DIV-914 | 914 F, 914 UL | 0 | 0 | 01.01.2001 | | Monitoring-Program TLR 4.3a |
| DIV-914 | 914 F, 914 UL | 0 | 1 | 18.11.2015 | | Monitoring-Program TLR 4.6a |
| IM-275 | 275 | 1 | 0 | 01.11.1990 | | Installation Manual 275 (not available - use german version) |
| IM-447 | 447 UL, 503 UL, 582 UL | 0 | 0 | 01.05.1999 | 899482 | Installation Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99 |
| IM-463 | 463 | 1 | 0 | 01.04.1992 | | Installation Manual 463 - (not available - use german version) |
| IM-503 | 447 UL, 503 UL, 582 UL | 0 | 0 | 01.05.1999 | 899482 | Installation Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99 |
| IM-535 | 535 A, 535 B, 535 C | 1 | 0 | 01.12.1982 | | Installation Manual 535 (Serie) - (not available - use german version) |
| IM-582 | 447 UL, 503 UL, 582 UL | 0 | 0 | 01.05.1999 | 899482 | Installation Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99 |
| IM-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 2 | 1 | 01.02.2015 | 898643 | Installation Manual ROTAX 912 Series |
| IM-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 2 | 1 | 01.02.2015 | 898642 | Revision Pages for Installation Manual ROTAX 912 Series, Issue 2, Revision 1 |
| IM-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 1 | 3 | 01.08.2015 | 898647 | Installation Manual ROTAX 912 i Series, Rev. 3 |
| IM-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 1 | 3 | 01.08.2015 | | Revision pages for Installation Manual ROTAX 912 i Series, Rev. 3 |
| IM-914 | 914 F, 914 UL | 2 | 1 | 01.02.2015 | 897817 | Installation Manual 914 Series |
| IM-914 | 914 F, 914 UL | 2 | 1 | 01.02.2015 | | Revision Pages for Installation Manual 914 Series |
| IPC-185 | 185 | 0 | 0 | 01.01.1982 | n.a. | Spare parts list for engine 185 |
| IPC-275 | 275 | 0 | 0 | 01.07.1988 | n.a. | Spare parts list for engine 275 (Nr. 656) |
| IPC-277 | 277 UL | 0 | 2 | 01.07.1993 | n.a. | Spare parts list for engine 277 UL (Nr. 491) |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|--|-------|----------|------------|--------|---|
| IPC-377 | 377 UL | 0 | 4 | 01.04.1993 | n.a. | Spare parts list for engine 377 UL (Nr. 624) |
| IPC-447 | 447 UL, 503 UL, 582 UL, 618 UL | 3 | 1 | 01.04.2011 | 899147 | Illustrated parts catalog for ROTAX 447 SCDI, 503 DCDI, 582 DCDI mod. 90, 582 DCDI mod. 99, 618 DCDI |
| IPC-462 | 462 UL | 0 | 0 | 01.10.1988 | n.a. | Spare parts list for engine 462 UL (Nr. 660) |
| IPC-501 | 501 | 1 | 0 | 01.01.1979 | n.a. | Spare parts list for engine 501 (Nr. 306) |
| IPC-503 | 447 UL, 503 UL, 582 UL, 618 UL | 3 | 1 | 01.04.2011 | 899147 | Illustrated parts catalog for ROTAX 447 SCDI, 503 DCDI, 582 DCDI mod. 90, 582 DCDI mod. 99, 618 DCDI |
| IPC-505 | 505, 505 A | 0 | 0 | 01.09.1990 | n.a. | parts list for engine type 505/505A (Nr. 744) |
| IPC-505 | 505 A | 1 | 1 | 01.07.1993 | n.a. | Spare parts list for engine 505 A (Nr. 805) |
| IPC-508 | 508 UL | 0 | 0 | 01.08.1988 | n.a. | Spare parts list for engine 508 (Nr. 646) |
| IPC-532-000 | 532 UL | 0 | 2 | 01.07.1993 | n.a. | Spare parts list for engine 532 UL (Nr. 648) |
| IPC-535 | 535 C | 0 | 0 | 01.04.1988 | n.a. | Illustrated Parts Catalog 535 C (Nr. 645) |
| IPC-535 | 535 A, 535 B | 0 | 0 | 01.07.1983 | n.a. | Illustrated Parts Catalog 535 A+B (Nr. 448) |
| IPC-582 | 447 UL, 503 UL, 582 UL, 618 UL | 3 | 1 | 01.04.2011 | 899147 | Illustrated parts catalog for ROTAX 447 SCDI, 503 DCDI, 582 DCDI mod. 90, 582 DCDI mod. 99, 618 DCDI |
| IPC-618 | 447 UL, 503 UL, 582 UL, 618 UL | 3 | 1 | 01.04.2011 | 899147 | Illustrated parts catalog for ROTAX 447 SCDI, 503 DCDI, 582 DCDI mod. 90, 582 DCDI mod. 99, 618 DCDI |
| IPC-912 | 912 UL | 0 | 1 | 01.11.1994 | n.a. | Illustrated parts catalog 912 UL (No. 825) |
| IPC-912 | 912 A, 912 UL | 0 | 3 | 01.07.1992 | n.a. | Illustrated parts catalog 912 UL (No. 700) |
| IPC-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 3 | 2 | 01.02.2016 | 899472 | Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL |
| IPC-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 3 | 2 | 01.02.2016 | | Exchange pages for Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL, Edition 3, Revision 2 |
| IPC-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 2 | 0 | 01.06.2015 | 899475 | Illustrated Parts Catalog for ROTAX Engine Type 912 i Series |
| IPC-914 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 3 | 2 | 01.02.2016 | 899472 | Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL |
| IPC-914 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 3 | 2 | 01.02.2016 | | Exchange pages for Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL, Edition 3, Revision 2 |
| MM-447 | 447 UL, 503 UL, 582 UL | 0 | 0 | 01.05.1999 | 899484 | Maintenance Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99 |
| MM-503 | 447 UL, 503 UL, 582 UL | 0 | 0 | 01.05.1999 | 899484 | Maintenance Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99 |
| MM-582 | 447 UL, 503 UL, 582 UL | 0 | 0 | 01.05.1999 | 899484 | Maintenance Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99 |
| MMH-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 1 | 4 | 01.02.2015 | 899603 | Maintenance Manual (Heavy) for ROTAX 912 and 914 Series |
| MMH-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 1 | 4 | 01.02.2015 | | Revision Pages for Maintenance Manual (Heavy) for ROTAX 912 and 914 Series, Rev. 4 |
| MMH-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 1 | 2 | 01.09.2014 | 898751 | Maintenance Manual (Heavy) for ROTAX 912 i Series |
| MMH-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 1 | 2 | 01.09.2014 | | Revision pages for Maintenance Manual Heavy for ROTAX 912 i Series |
| MMH-914 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 1 | 4 | 01.02.2015 | 899603 | Maintenance Manual (Heavy) for ROTAX 912 and 914 Series |
| MMH-914 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 1 | 4 | 01.02.2015 | | Revision Pages for Maintenance Manual (Heavy) for ROTAX 912 and 914 Series, Rev. 4 |
| MML-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 3 | 2 | 01.02.2015 | 899191 | Maintenance Manual 912 Series (Line Maintenance) |
| MML-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 3 | 2 | 01.02.2015 | | Revision Pages for Maintenance Manual 912 Series (Line Maintenance), Revision 2 |
| MML-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 2 | 01.06.2014 | | Revision pages for Maintenance Manual (Line) for ROTAX 912 i Series, Rev. 2 |
| MML-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 1 | 2 | 01.06.2014 | 898742 | Maintenance Manual (Line) ROTAX 912 i Series |
| MML-914 | 914 F, 914 UL | 2 | 2 | 01.02.2015 | 899608 | Maintenance Manual (Line) for ROTAX 914 Series |
| MML-914 | 914 F, 914 UL | 2 | 2 | 01.02.2015 | | Revision Pages for Maintenance Manual (Line) for 914 Series |
| OHM-503 | 503 UL | 0 | 0 | | n.a. | Overhaul Manual ROTAX 503 UL DCDI (not available) |
| OHM-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 2 | 3 | 01.04.2015 | 898701 | Overhaul Manual 912 and 914 Series (only available for authorized distributors and overhaul facilities) |
| OHM-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 1 | 0 | 01.04.2014 | 898706 | Overhaul Manual 912 i Series (only available for authorized distributors and overhaul facilities) |
| OHM-914 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 2 | 3 | 01.04.2015 | 898701 | Overhaul Manual 912 and 914 Series (only available for authorized distributors and overhaul facilities) |
| OHMA-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 1 | 5 | 01.03.2016 | 897797 | Appendix to Overhaul Manual 912 and 914 Series, only available in English language (only available for authorized distributors and overhaul facilities) |
| OHMA-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 1 | 1 | 01.04.2014 | 898744 | Appendix to Overhaul Manual 912 i Series, only available in English language (only available for authorized distributors and overhaul facilities) |
| OHMA-914 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 1 | 5 | 01.03.2016 | 897797 | Appendix to Overhaul Manual 912 and 914 Series, only available in English language (only available for authorized distributors and overhaul facilities) |
| OM-275 | 275 | 1 | 2 | 15.01.1998 | n.a. | Operator's manual 275 |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|----------------|---|-------|----------|------------|--------|---|
| OM-277 | 277 UL | 0 | 4 | 01.03.1988 | n.a. | Operators manual 277 UL |
| OM-377-000 | 377 UL, 447 UL, 503 UL | 19 | 0 | 01.06.1994 | n.a. | Operator's Manual 377-447-503 UL CB |
| OM-447 | 447 UL, 503 UL, 582 UL | 2 | 0 | 01.09.2010 | 899121 | Operators Manual for engine types 447 UL SCDI, 503 UL DCDI, 582 UL DCDI mod. 90 and 582 UL DCDI mod. 99 |
| OM-447-000 | 377 UL, 447 UL, 503 UL | 19 | 0 | 01.06.1994 | n.a. | Operator's Manual 377-447-503 UL CB |
| OM-462 | 462 UL | 0 | 2 | 01.07.1993 | 897623 | Operators manual 462 UL |
| OM-463 | 463 | 1 | 0 | 12.06.1992 | n.a. | Operator's manual 463 - (not available - use german version) |
| OM-501 | 501 | 1 | 2 | 01.11.1997 | n.a. | Operator's manual 501 |
| OM-503 | 447 UL, 503 UL, 582 UL | 2 | 0 | 01.09.2010 | 899121 | Operators Manual for engine types 447 UL SCDI, 503 UL DCDI, 582 UL DCDI mod. 90 and 582 UL DCDI mod. 99 |
| OM-503-000 | 377 UL, 447 UL, 503 UL | 19 | 0 | 01.06.1994 | n.a. | Operator's Manual 377-447-503 UL CB |
| OM-505 | 505 | 2 | 0 | 30.04.1992 | n.a. | Operator's manual 505 with decompressor |
| OM-505 | 505 | 2 | 0 | 30.04.1992 | n.a. | Operator's manual 505 without decompressor |
| OM-505 | 505 A | 2 | 0 | 29.01.1992 | n.a. | Operators manual 505 A without decompressor |
| OM-505 | 505 A | 2 | 0 | 30.04.1992 | n.a. | Operator's manual 505 A with decompressor |
| OM-508 | 508 UL | 0 | 3 | 01.07.1993 | n.a. | Operators manual 508 UL |
| OM-532 | 532 UL | 0 | 4 | 01.03.1990 | n.a. | Operators manual 532 UL |
| OM-535 | 535 A, 535 B | 2 | 0 | 01.01.1992 | n.a. | Operator's manual 535 A (dual carburetor horizontal) Operator's manual 535 B (dual carburetor vertical) |
| OM-535-000 | 535 C | 2 | 0 | 01.01.1992 | n.a. | Operator's manual 535 C (single carburetor) |
| OM-582 | 447 UL, 503 UL, 582 UL | 2 | 0 | 01.09.2010 | 899121 | Operators Manual for engine types 447 UL SCDI, 503 UL DCDI, 582 UL DCDI mod. 90 and 582 UL DCDI mod. 99 |
| OM-618-000 | 618 UL | 1 | 0 | 01.06.1994 | n.a. | Operators manual ROTAX 618 UL (preliminary) |
| OM-642 | 642 | 0 | 0 | 01.06.1975 | n.a. | Operator's manual 642 |
| OM-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 3 | 2 | 01.02.2015 | 899649 | Operators Manual 912 Series |
| OM-912 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 3 | 2 | 01.02.2015 | | Revision Pages for Operators Manual 912 Series, Revision 2 |
| OM-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 1 | 3 | 01.08.2015 | 898740 | Operators Manual ROTAX 912 i Series, Rev. 2 |
| OM-912i | 912 iS, 912 iS Sport, 912 iSc Sport | 1 | 3 | 01.08.2015 | | Revision pages for Operators Manual ROTAX 912 i Series, Rev.3 |
| OM-914 | 914 F, 914 UL | 2 | 2 | 01.02.2015 | 899645 | Operators Manual 914 Series |
| OM-914 | 914 F, 914 UL | 2 | 2 | 01.02.2015 | 899645 | Revision Pages for Operators Manual 914 Series, Revision 2 |
| RM-275 | 275 | 1 | 1 | 01.10.1991 | n.a. | Repair manual 275 |
| RM-277 | 277 UL | 0 | 2 | 01.01.1993 | n.a. | Repair manual 277 UL |
| RM-377 | 377 UL, 447 UL, 503 UL | 0 | 1 | 01.12.1989 | n.a. | Repair manual engine types 377-447-503 UL CB |
| RM-447 | 377 UL, 447 UL, 503 UL | 0 | 1 | 01.12.1989 | n.a. | Repair manual engine types 377-447-503 UL CB |
| RM-462 | 462 UL, 532 UL, 582 UL | 0 | 1 | 01.10.1994 | 899081 | Repair manual 462-532-582 UL |
| RM-501 | 501, 505, 505 A | 1 | 3 | 01.01.1993 | n.a. | Repair manual 501/505 (Serie) |
| RM-503 | 503 UL | 0 | 0 | 02.07.2013 | n.a. | Repair Manual ROTAX 503 UL DCDI (not available) |
| RM-503 | 377 UL, 447 UL, 503 UL | 0 | 1 | 01.12.1989 | n.a. | Repair manual engine types 377-447-503 UL CB |
| RM-505 | 501, 505, 505 A | 1 | 3 | 01.01.1993 | n.a. | Repair manual 501/505 (Serie) |
| RM-532 | 462 UL, 532 UL, 582 UL | 0 | 1 | 01.10.1994 | 899081 | Repair manual 462-532-582 UL |
| RM-535-000 | 535 A, 535 B, 535 C | 1 | 0 | 01.01.1993 | n.a. | Repair manual 535 (Serie) |
| RM-582 | 462 UL, 532 UL, 582 UL | 0 | 1 | 01.10.1994 | 899081 | Repair manual 462-532-582 UL |
| **SB-275 | 275, 501, 505, 505 A, 535 A, 535 B, 535 C | 0 | 1 | 04.05.2007 | | New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535 |
| **SB-501 | 501, 505, 505 A | 0 | 0 | 01.08.1989 | n.a. | Piston pin bearing, conversion to reinforced design **(for 501 see SB-505-005) |
| **SB-501 | 501, 505, 505 A | 0 | 0 | 02.12.1997 | n.a. | TBO of ROTAX engine type 501, 505 and 505 A. **(for 501 see SB-505-007) |
| **SB-501 | 275, 501, 505, 505 A, 535 A, 535 B, 535 C | 0 | 1 | 04.05.2007 | | New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535 |
| ASB-912-051 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 13.10.2006 | | CANCELLED - Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition |
| ASB-912-051-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 13.10.2006 | | CANCELLED - Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition |
| ASB-912-053 | 912 A, 912 F, 912 S | 0 | 0 | 20.02.2007 | | Replacement of fuel pump for Rotax engine type 912 (Series) - replaced by SB-912-053, latest edition |
| ASB-912-053-UL | 912 UL, 912 ULS, 912 ULSFR | 0 | 0 | 20.02.2007 | | Replacement of fuel pump for Rotax engine type 912 (Series) - replaced by SB-912-053, latest edition |
| ASB-912-059 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.01.2012 | | CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059/SB-914-042 latest edition |
| ASB-912-059-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.01.2012 | | CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059UL/SB-914-042UL latest edition |
| ASB-912-060 | 912 S, 914 F | 0 | 0 | 26.01.2012 | | Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series) |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|-----------------|---|-------|----------|------------|-------|---|
| ASB-912-060-UL | 912 UL, 912 ULS, 914 UL | 0 | 0 | 26.01.2012 | | Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series) |
| ASB-912-061 | 912 A, 912 F, 912 S | 0 | 1 | 31.05.2012 | | Replacement of the pressure side fuel hose at fuel pump part no. 893114 for ROTAX engine type 912 (Series) |
| ASB-912-061-UL | 912 UL, 912 ULS | 0 | 1 | 31.05.2012 | | Replacement of the pressure side fuel hose at fuel pump part no. 893114 for ROTAX engine type 912 (Series) |
| ASB-912-062 | 912 A, 912 F, 912 S, 914 F | 0 | 2 | 29.05.2013 | | Checking of the cylinder head assy. 2/3 for ROTAX engine type 912 and 914 (Series) |
| ASB-912-062-UL | 912 UL, 912 ULS, 914 UL | 0 | 2 | 29.05.2013 | | Checking of the cylinder head assy. 2/3 for ROTAX engine type 912 and 914 (Series) |
| ASB-912i-005-iS | 912 iS, 912 iS Sport | 0 | 0 | 29.05.2015 | | The use of lithium-ion batteries in combination with the ROTAX engine type 912 i Series |
| ASB-914-034 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 13.10.2006 | | CANCELLED - Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition |
| ASB-914-034-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 13.10.2006 | | CANCELLED - Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition |
| ASB-914-042 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.01.2012 | | CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059/SB-914-042 latest edition |
| ASB-914-042-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.01.2012 | | CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059UL/SB-914-042UL latest edition |
| ASB-914-043 | 912 S, 914 F | 0 | 0 | 26.01.2012 | | Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series) |
| ASB-914-043-UL | 912 UL, 912 ULS, 914 UL | 0 | 0 | 26.01.2012 | | Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series) |
| ASB-914-044 | 912 A, 912 F, 912 S, 914 F | 0 | 2 | 29.05.2013 | | Checking of the cylinder head assy. 2/3 for ROTAX engine type 912 and 914 (Series) |
| ASB-914-044-UL | 912 UL, 912 ULS, 914 UL | 0 | 2 | 29.05.2013 | | Checking of the cylinder head assy. 2/3 for ROTAX engine type 912 and 914 (Series) |
| SB-2ST-000 | 185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 642, 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 20 | 20.06.2016 | | Publication Index for ROTAX Aircraft Engines |
| SB-2ST-001 | 582 UL | 0 | 0 | 01.12.2001 | n.a. | Checking or replacement of tension spring on exhaust system for ROTAX engine type 582 UL |
| SB-2ST-002 | 582 UL | 0 | 0 | 01.03.2002 | n.a. | Modified rotary valve cover for ROTAX engine type 582 UL |
| SB-505-000 | 505, 505 A, 535 A, 535 B, 535 C, 912 A, 912 F, 912 S, 914 F | 0 | 0 | 20.06.2016 | | Publication Index for ROTAX Aircraft Engines |
| SB-505-001 | 505 | 0 | 0 | 26.02.1986 | n.a. | Studs 840 585 (M8x177) connecting cylinders to crankcase (8x) |
| SB-505-002 | 505 | 0 | 0 | 20.09.1988 | n.a. | Conversion of engine types 505 into 505 A (type certificate data sheet TW 3/78, issue no. 5) |
| SB-505-003 | 505, 505 A | 0 | 0 | 20.09.1988 | n.a. | Check of ignition timing after exchange of an electronic box |
| SB-505-004 | 505, 505 A | 0 | 0 | 13.04.1989 | n.a. | Examination of the starter gear for cracks. |
| SB-505-005 | 501, 505, 505 A | 0 | 0 | 01.08.1989 | n.a. | Piston pin bearing, conversion to reinforced design ** (for 501 see SB-505-005) |
| SB-505-006 | 505, 505 A | 0 | 0 | 29.01.1992 | n.a. | Introduction of a new electronic box with a modified wiring on the stator plate. |
| SB-505-007 | 501, 505, 505 A | 0 | 0 | 02.12.1997 | n.a. | TBO of ROTAX engine type 501, 505 and 505 A. ** (for 501 see SB-505-007) |
| SB-505-008 | 505, 505 A | 0 | 0 | 22.01.1999 | n.a. | Magneto housing for ROTAX engine type 505 (series) |
| SB-505-009 | 505, 505 A | 0 | 1 | 01.03.2003 | n.a. | New charging coil assy. with support for Rotax engine type 505 |
| SB-505-010 | 275, 501, 505, 505 A, 535 A, 535 B, 535 C | 0 | 1 | 04.05.2007 | | New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535 |
| SB-535-000 | 505, 505 A, 535 A, 535 B, 535 C, 912 A, 912 F, 912 S, 914 F | 0 | 0 | 20.06.2016 | | Publication Index for ROTAX Aircraft Engines |
| SB-535-001 | 535 A, 535 B | 0 | 0 | 31.01.1984 | n.a. | Flywheel on drive side |
| SB-535-002 | 535 A, 535 B | 0 | 0 | 05.12.1985 | n.a. | Coil brace 866 780 connecting charging coil with lighting coil on armature plate assy. |
| SB-535-003 | 535 A, 535 B, 535 C | 0 | 0 | 20.09.1988 | n.a. | Check of ignition timing after exchange of an electronic box. |
| SB-535-004 | 535 A, 535 B, 535 C | 0 | 0 | 21.03.1989 | n.a. | Fixation of charging coil and lighting coil on armature plate assy. |
| SB-535-005 | 535 A, 535 B, 535 C | 0 | 0 | 13.04.1989 | n.a. | Examination of the starter gear for cracks. |
| SB-535-006 | 535 A, 535 B, 535 C | 0 | 0 | 05.06.1992 | n.a. | Introduction of a new electronic box with a modified wiring on the stator plate. |
| SB-535-007 | 535 A, 535 B, 535 C | 0 | 1 | 01.02.1999 | n.a. | Magneto housing for ROTAX engine type 535 (series). |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|---|-------|----------|------------|--------|--|
| SB-535-008 | 535 A, 535 B, 535 C | 0 | 1 | 28.01.2005 | n.a. | New charging coil assy. with support for Rotax engine type 535 |
| SB-535-009 | 275, 501, 505, 505 A, 535 A, 535 B, 535 C | 0 | 1 | 04.05.2007 | | New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535 |
| SB-912-000 | 505, 505 A, 535 A, 535 B, 535 C, 912 A, 912 F, 912 S, 914 F | 0 | 20 | 20.06.2016 | | Publication Index for ROTAX Aircraft Engines |
| SB-912-000UL | 185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 642, 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 20.06.2016 | | Publication Index for ROTAX Aircraft Engines |
| SB-912-001 | 912 A | 0 | 0 | 13.08.1992 | 897681 | Engine type 912 A, Ignition unit with resistor spark plug |
| SB-912-002 | 912 A | 0 | 1 | 29.11.1993 | n.a. | Ignition for ROTAX 912 A |
| SB-912-003 | 912 A | 0 | 0 | 28.09.1993 | n.a. | CANCELLED - Operators manual for ROTAX 912 A - superseded by Operators manual 912 Series, current edition |
| SB-912-004 | 912 A | 0 | 2 | 14.12.2009 | n.a. | Extension of time between overhauls (TBO) for ROTAX engine type 912 A (Series) |
| SB-912-004-UL | 912 UL | 0 | 2 | 14.12.2009 | n.a. | Extension of time between overhauls (TBO) for ROTAX engine type 912 UL (Series) |
| SB-912-005 | 912 A | 0 | 2 | 29.07.1996 | n.a. | Special inspection to increase the TBO for engine 912 A Serie |
| SB-912-005 | 912 A | 0 | 3 | 14.12.2009 | n.a. | Special inspection to increase the TBO for ROTAX engine type 912 A (Series) |
| SB-912-005-UL | 912 UL | 0 | 0 | 14.12.2009 | n.a. | Special inspection to increase the TBO for ROTAX engine type 912 UL (Series) |
| SB-912-006 | 912 A | 0 | 0 | 28.11.1994 | n.a. | Grounding cable for electronic module of ROTAX Engine series Type 912 A |
| SB-912-007 | 912 A | 0 | 0 | 01.02.1995 | n.a. | Ground connection for pick up wiring, ROTAX Engine Series Type 912 A |
| SB-912-007-UL | 912 UL | 0 | 0 | 20.12.2007 | | Ground connection for pick-up wiring for ROTAX engine type 912 (Series) |
| SB-912-008 | 912 A | 0 | 0 | 24.08.1995 | n.a. | Electronic module with pi-filter, ROTAX Engine Series 912 A |
| SB-912-009 | 912 A | 0 | 0 | 12.09.1995 | n.a. | Contamination of carburetors, ROTAX 912 A (series) |
| SB-912-010 | 912 A, 912 F | 0 | 0 | 08.02.1996 | n.a. | Fitting of a carburetor support, ROTAX 912 A/F (series) |
| SB-912-010-UL | 912 UL | 0 | 0 | 20.12.2007 | | Fitting of a carburetor support for ROTAX engine type 912 (Series) |
| SB-912-011 | 912 A, 912 F | 0 | 1 | 01.11.1999 | n.a. | CANCELLED - Use of an adapted propeller governor on Rotax engine type 912 A3 and 912 F3, superseded by SB-912-052/SB-914-035, latest edition |
| SB-912-012 | 912 A | 0 | 0 | 13.08.1996 | n.a. | Modification on ROTAX 912 A4 |
| SB-912-013 | 912 A, 912 F, 912 S, 912 UL, 912 ULS | 0 | 0 | 29.07.1996 | n.a. | CANCELLED - Motor oil for ROTAX 912 Series - superseded by SI-18-1997 latest edition |
| SB-912-014 | 912 A, 912 F | 0 | 2 | 14.12.2009 | n.a. | Extension of time between overhauls (TBO) for ROTAX engine type 912 A and 912 F (Series) |
| SB-912-015 | 912 A, 912 F | 0 | 0 | 29.07.1996 | n.a. | Replacement of rocker arms on ROTAX 912 A/F (series) |
| SB-912-015-UL | 912 UL | 0 | 0 | 20.12.2007 | | Replacement of rocker arms for ROTAX engine type 912 (Series) |
| SB-912-016 | 912 A | 0 | 0 | 13.08.1996 | n.a. | External alternator for engine type 912, model A2, A3 and A4 |
| SB-912-017 | 912 A, 912 F | 0 | 1 | 20.12.2007 | n.a. | Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series) |
| SB-912-017-UL | 912 UL | 0 | 1 | 20.12.2007 | | Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series) |
| SB-912-018 | 912 A | 0 | 1 | 18.03.1997 | n.a. | Cam shaft check engine type ROTAX 912 A (series) |
| SB-912-019 | 912 A | 0 | 0 | 09.07.1997 | n.a. | Propeller gear box for ROTAX 912 A3 |
| SB-912-020 | 912 A, 912 F | 0 | 1 | 10.02.1998 | 897682 | Fuel pump for Engine type ROTAX 912 F and 912 A (series) |
| SB-912-020-UL | 912 UL | 0 | 0 | 20.12.2007 | | Replacement of the fuel pump part no. 996592 for ROTAX engine type 912 (Series) |
| SB-912-021 | 912 F | 0 | 0 | 17.12.1997 | n.a. | CANCELLED - Operator's manual for ROTAX 912 F - superseded by Operator's manual 912 Series, latest edition |
| SB-912-022 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.03.2001 | 898081 | Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (series) |
| SB-912-022-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 13.03.2001 | 898083 | Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (Series) |
| SB-912-023 | 912 A, 912 F | 0 | 0 | 25.05.1998 | n.a. | Inspection of the fuel pump kit, part no. 996.594 ³ |
| SB-912-024 | 912 A, 912 F | 0 | 0 | 22.10.1998 | n.a. | CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T1, superseded by SB-912-052/SB-914-035, latest edition |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|------------------------------------|-------|----------|------------|--------|--|
| SB-912-025 | 912 A, 912 F | 0 | 0 | 22.10.1998 | n.a. | CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T2, superseded by SB-912-052/SB-914-035, latest edition |
| SB-912-026 | 912 A, 912 F, 914 F | 0 | 3 | 01.12.1999 | n.a. | Checking and replacement of stator assy. |
| SB-912-026-UL | 912 UL, 912 ULS, 914 UL | 0 | 3 | 01.12.1999 | n.a. | Checking and replacement of stator assy. |
| SB-912-027 | 912 A, 912 F, 914 F | 0 | 1 | 01.02.2000 | n.a. | Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914 |
| SB-912-027-UL | 912 UL, 914 UL | 0 | 1 | 01.02.2000 | n.a. | Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914 |
| SB-912-028 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 01.11.2002 | n.a. | Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (Series) |
| SB-912-028-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 01.11.2002 | n.a. | Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (series) |
| SB-912-029 | 912 A, 912 F, 912 S, 914 F | 0 | 3 | 11.07.2006 | n.a. | Checking of crankcase on ROTAX engine type 912 and 914 (Series) |
| SB-912-029-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 3 | 11.07.2006 | n.a. | Checking of the crankcase on ROTAX engine type 912 and 914 (Series) |
| SB-912-030 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 01.02.2004 | n.a. | Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series) |
| SB-912-030-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 01.02.2004 | n.a. | Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series) |
| SB-912-031 | 912 A, 912 F, 912 S | 0 | 0 | 01.10.2001 | n.a. | Checking or replacement of the fuel pump assembly part no. 996 596 on ROTAX engine type 912 (series) |
| SB-912-031-UL | 912 UL, 912 ULS, 912 ULSFR | 0 | 0 | 01.10.2001 | n.a. | Checking or replacement of the fuel pump assembly part no. 996 596 on ROTAX engine type 912 (series) |
| SB-912-032 | 912 A | 0 | 0 | 01.10.2001 | 898181 | Replacement of oil pump assy. or oil pump shaft assy. on ROTAX engine type 912 A (series) |
| SB-912-032-UL | 912 UL | 0 | 0 | 01.10.2001 | 898183 | Replacement of oil pump assy. or oil pump shaft assy. on ROTAX engine type 912 UL |
| SB-912-033 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.08.2002 | n.a. | Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914 |
| SB-912-033-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.08.2002 | n.a. | Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914 |
| SB-912-034 | 912 A | 0 | 0 | 01.03.2002 | n.a. | Checking of oil pump attachment screw for ROTAX engine type 912 A (Series) |
| SB-912-034-UL | 912 UL | 0 | 0 | 01.03.2002 | n.a. | Checking of oil pump attachment screw for ROTAX engine type 912 UL (Series) |
| SB-912-035 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 01.09.2002 | n.a. | Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series) |
| SB-912-035-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 01.09.2002 | n.a. | Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series) |
| SB-912-036 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 23.01.2007 | n.a. | CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040/SB-914-026, latest edition |
| SB-912-036-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 23.01.2007 | n.a. | CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040UL/SB-914-026UL, latest edition |
| SB-912-037 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 01.10.2003 | n.a. | Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie) |
| SB-912-037-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.10.2002 | n.a. | Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie) |
| SB-912-038 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.11.2002 | | CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series) |
| SB-912-038-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.11.2002 | | CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series) |
| SB-912-039 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.12.2002 | | Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series) |
| SB-912-039-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.12.2002 | | Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series) |
| SB-912-040 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 01.08.2003 | | Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series) |
| SB-912-040-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.04.2003 | | Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series) |
| SB-912-041 | 912 A, 912 F, 912 S, 914 F | 0 | 2 | 25.03.2010 | | Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series) |
| SB-912-041-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 2 | 25.03.2010 | | Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series) |
| SB-912-042 | 912 S | 0 | 1 | 01.04.2004 | n.a. | Checking of the engine in case of excessive propeller backlash for Rotax engine type 912 S |
| SB-912-042-UL | 912 ULS, 912 ULSFR | 0 | 1 | 01.04.2004 | n.a. | Checking of the engine in case of excessive propeller backlash for Rotax engine type 912 S |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|------------------------------------|-------|----------|------------|-------|---|
| SB-912-043 | 912 A, 912 F, 912 S, 914 F | 0 | 2 | 10.11.2006 | | Change of coolant specification on ROTAX engine type 912 and 914 (Series) |
| SB-912-043-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 28.08.2006 | | Change of coolant specification on ROTAX engine type 912 and 914 (Series) |
| SB-912-044 | 912 A, 912 F | 0 | 1 | 28.05.2010 | | Use of the Rotax supplied airbox for all Rotax engine types 912 A/F (Series) |
| SB-912-044-UL | 912 UL | 0 | 1 | 28.05.2010 | | Use of the Rotax supplied airbox for all Rotax engine types 912 UL (Series) |
| SB-912-045 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 19.11.2004 | | Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series) |
| SB-912-045-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 19.11.2004 | | Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series) |
| SB-912-046 | 912 S, 914 F | 0 | 0 | 26.07.2005 | | Check of the support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series) |
| SB-912-046-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 26.07.2005 | | Check of support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series) |
| SB-912-047 | 912 S, 914 F | 0 | 0 | 29.07.2005 | | Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series) |
| SB-912-047-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 29.07.2005 | | Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series) |
| SB-912-048 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 23.09.2005 | | Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series) |
| SB-912-048-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 23.09.2005 | | Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series) |
| SB-912-049 | 912 A, 912 F, 912 S | 0 | 0 | 24.05.2006 | | Checking eccenters and fuel pump plungers for Rotax engine type 912 (series) |
| SB-912-049-UL | 912 UL, 912 ULS, 912 ULSFR | 0 | 0 | 24.05.2006 | | Checking eccenters and fuel pump plungers for Rotax engine type 912 (series) |
| SB-912-050 | 912 A, 912 F, 912 S | 0 | 0 | 24.05.2006 | | CANCELLED - Checking or replacement of fuel pump part no. 892230/892235 on Rotax engine type 912 (series), superseded by ASB-912-053 latest edition |
| SB-912-050-UL | 912 UL, 912 ULS, 912 ULSFR | 0 | 0 | 24.05.2006 | | CANCELLED - Checking or replacement of fuel pump part no. 892230/892235 on Rotax engine type 912 (series), superseded by ASB-912-053 latest edition |
| SB-912-051 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 30.01.2008 | | Checking of magnetic plug on Rotax engine type 912/914 (Series) |
| SB-912-051-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 30.01.2008 | | Checking of magnetic plug on Rotax engine type 912/914 (Series) |
| SB-912-052 | 912 A, 912 F, 912 S, 914 F | 0 | 4 | 13.06.2014 | | Installation / Use of governors for Rotax engine type 912 and 914 |
| SB-912-052-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 3 | 13.06.2014 | | Installation / Use of governors for Rotax engine type 912i, 912 and 914 (Series) |
| SB-912-053 | 912 A, 912 F, 912 S | 0 | 0 | 13.04.2007 | | Replacement of fuel pump for Rotax engine type 912 (Series) |
| SB-912-053-UL | 912 UL, 912 ULS, 912 ULSFR | 0 | 0 | 13.04.2007 | | Replacement of fuel pump for Rotax engine type 912 (Series) |
| SB-912-054 | 912 A, 912 F, 912 S | 0 | 0 | 29.05.2007 | | Checking or replacement of flexible fuel line for Rotax engine type 912 (Series) |
| SB-912-054-UL | 912 UL, 912 ULS, 912 ULSFR | 0 | 0 | 29.05.2007 | | Checking or replacement of flexible fuel line for Rotax engine type 912 (Series) |
| SB-912-055 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 31.08.2007 | | Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series) |
| SB-912-055-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 31.08.2007 | | Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series) |
| SB-912-056 | 912 S, 914 F | 0 | 1 | 05.08.2008 | | Replacement of the propeller gearbox for some Rotax engines type 912/914 (Series) |
| SB-912-056-UL | 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 05.08.2008 | | Replacement of the propeller gearbox for some ROTAX engines type 912/914 (Series) |
| SB-912-057 | 912 A, 912 F, 912 S | 0 | 1 | 24.05.2016 | | Extension of time between overhauls (TBO) for ROTAX engine type 912 (Series) |
| SB-912-057-UL | 912 UL, 912 ULS, 912 ULSFR | 0 | 0 | 14.12.2009 | | Extension of time between overhauls (TBO) for ROTAX engine type 912 (Series) |
| SB-912-058 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 15.04.2011 | | Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series) |
| SB-912-058-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 15.04.2011 | | Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series) |
| SB-912-059 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.01.2012 | | Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series) |
| SB-912-059-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.01.2012 | | Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series) |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|----------------|---|-------|----------|------------|-------|---|
| SB-912-063 | 912 A, 912 F, 912 S | 0 | 1 | 24.06.2013 | | Replacement of Fuel Pumps for Rotax Engine Type 912 (Series) |
| SB-912-063-UL | 912 UL, 912 ULS, 912 ULSFR | 0 | 2 | 21.08.2013 | | Replacement of Fuel Pumps for Rotax Engine Type 912 (Series) |
| SB-912-064 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 11.11.2013 | | Periodic checking of the crankshaft journal (power take off side) for ROTAX Engine Type 912 and 914 (Series) |
| SB-912-064-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 11.11.2013 | | Periodic checking of the crankshaft journal (power take off side) for ROTAX Engine Type 912 and 914 (Serie) |
| SB-912-065 | 912 A, 912 F, 912 S, 914 F | 0 | 3 | 26.03.2015 | | Periodic inspection of the float buoyancy for ROTAX Engine Type 912 and 914 (Series) |
| SB-912-065-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 3 | 26.03.2015 | | Periodic inspection of the float buoyancy for ROTAX Engine Type 912 and 914 (Series) |
| SB-912-066 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 23.04.2015 | | Change of Measurement Method from Cylinder Head Temperature to Coolant Temperature for ROTAX® Engine Type 912 and 914 (Series) |
| SB-912-066-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 23.04.2015 | | Change of Measurement Method from Cylinder Head Temperature to Coolant Temperature for ROTAX® Engine Type 912 and 914 (Series) |
| SB-912-067 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 26.03.2015 | | Exchange of floats on ROTAX Engine Type 912 and 914 (Series) |
| SB-912-067-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 26.03.2015 | | Echange of floats on ROTAX Engine Type 912 and 914 (Series) |
| SB-912-068 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 09.09.2015 | | Specification/Change of Engine Configuration and/or Type Plate for ROTAX Engine Type 912 and 914 (Series) |
| SB-912-068-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 2 | 09.09.2015 | | Specification/Change of Engine Configuration and/or Type Plate for ROTAX Engine Type 912 and 914 (Series) |
| SB-912i-000 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 8 | 20.06.2016 | | Publication Index for ROTAX Aircraft Engines |
| SB-912i-001 | 912 iS, 912 iSc Sport | 0 | 1 | 13.06.2014 | | Installation / Use of governors for Rotax engine type 912i, 912 and 914 Series |
| SB-912i-001-iS | 912 iS, 912 iS Sport | 0 | 1 | 13.06.2014 | | Installation / Use of governors for Rotax engine type 912i, 912 and 914 Series |
| SB-912i-002-iS | 912 iS | 0 | 0 | 18.12.2013 | | Flashing of a new Software on the Engine Control Unit 912 iS (ECU) for ROTAX Engine Type 912 i (Series) |
| SB-912i-003-iS | 912 iS | 0 | 1 | 03.06.2014 | | Installation instructions for upgrade kit 912 iS Sport for ROTAX engine type 912 i (Series) |
| SB-912i-004-iS | 912 iS | 0 | 0 | 03.09.2014 | | Replacement of Regulator A and Regulator B for ROTAX Engine Type 912 i (Series) |
| SB-912i-006 | 912 iSc Sport | 0 | 0 | 26.05.2016 | | Exchange of stator assy. of ROTAX Engine Type 912 i (Series) |
| SB-912i-006-iS | 912 iS, 912 iS Sport | 0 | 0 | 26.05.2016 | | Exchange of stator assy. of ROTAX Engine Type 912 i (Series) |
| SB-914-000 | 505, 505 A, 535 A, 535 B, 535 C, 912 A, 912 F, 912 S, 914 F | 0 | 20 | 20.06.2016 | | Publication Index for ROTAX Aircraft Engines |
| SB-914-000UL | 185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 642, 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 20.06.2016 | | Publication Index for ROTAX Aircraft Engines |
| SB-914-001 | 914 F | 0 | 0 | 06.02.1997 | n.a. | CANCELLED - Use of an adapted propeller governor on engine type ROTAX 914 F3, superseded by SB-912-052/SB-914-035, latest edition |
| SB-914-002 | 914 F | 0 | 0 | 24.02.1997 | n.a. | Modification of engine type ROTAX 914 F3 |
| SB-914-003 | 914 F | 0 | 0 | 09.07.1997 | n.a. | Calibration of the mixture enrichment jet of engine type ROTAX 914 F (series) |
| SB-914-003-UL | 914 UL | 0 | 0 | 20.12.2007 | | Calibration of the mixture enrichment jet for ROTAX engine type 914 (Series) |
| SB-914-004 | 914 F | 0 | 0 | 27.08.1997 | n.a. | Checking of the banjo bolt in the pressure oil line of turbo charger for ROTAX 914 (series) |
| SB-914-004-UL | 914 UL | 0 | 0 | 20.12.2007 | | Checking of the banjo bolt in the pressure oil line of turbocharger for ROTAX engine type 914 (Series) |
| SB-914-005 | 914 F | 0 | 0 | 29.07.1998 | n.a. | Introduction of a turbo charger with a modified wastegate on Rotax 914 |
| SB-914-005-UL | 914 UL | 0 | 0 | 20.12.2007 | | Introduction of a turbocharger with modified waste-gate for ROTAX engine type 914 (Series) |
| SB-914-006 | 914 F | 0 | 1 | 01.10.2002 | n.a. | Employment of a muffler of reduced noise emission on ROTAX engine Type 914 F (series). |
| SB-914-006-UL | 914 UL | 0 | 0 | 01.10.2002 | | Employment of a muffler of reduced noise emission on ROTAX engine Type 914 F (series). |
| SB-914-007 | 914 F | 0 | 0 | 05.06.1998 | n.a. | ROTAX engine type 914 F (series), check / replacement of the turbo oil pressure line and pipe clamps |
| SB-914-007-UL | 914 UL | 0 | 0 | 20.12.2007 | | Check/replacement of the turbo oil pressure line and pipe clamps for ROTAX engine type 914 (Series) |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|------------------------------------|-------|----------|------------|--------|--|
| SB-914-008 | 914 F | 0 | 0 | 05.06.1998 | n.a. | ROTAX engine type 914 F (series) check / replacement of the wastegate servo cable |
| SB-914-008-UL | 914 UL | 0 | 0 | 20.12.2007 | | Check/replacement of the waste-gate servo cable for ROTAX engine type 914 (Series) |
| SB-914-009 | 914 F | 0 | 0 | 22.10.1998 | n.a. | CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T2, superseded by SB-912-052/SB-914-035, latest edition |
| SB-914-010 | 912 A, 912 F, 914 F | 0 | 1 | 01.02.2000 | n.a. | Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914 |
| SB-914-010-UL | 912 UL, 914 UL | 0 | 1 | 01.02.2000 | n.a. | Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914 |
| SB-914-011 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.03.2001 | 898081 | Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (series) |
| SB-914-011-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 13.03.2001 | 898083 | Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (Series) |
| SB-914-012 | 914 F | 0 | 0 | 29.09.1998 | n.a. | ROTAX engine series type 914 F, verification of the wiring harness |
| SB-914-012-UL | 914 UL | 0 | 0 | 20.12.2007 | | Verification of the wiring harness for ROTAX engine type 914 (Series) |
| SB-914-013 | 914 F | 0 | 0 | 31.03.1999 | n.a. | Turbocharge control unit (TCU) with software level according to RTCA DO 178 B, for engine Type 914 F (series) |
| SB-914-013-UL | 914 UL | 0 | 0 | 20.12.2007 | | Turbocharge control unit (TCU) with software level D according to RTCA DO 178 B for ROTAX engine type 914 (Series) |
| SB-914-014 | 912 A, 912 F, 914 F | 0 | 3 | 01.12.1999 | n.a. | Checking and replacement of stator assy. |
| SB-914-014-UL | 912 UL, 912 ULS, 914 UL | 0 | 3 | 01.12.1999 | n.a. | Checking and replacement of stator assy. |
| SB-914-015 | 914 F | 0 | 0 | 01.01.2001 | n.a. | Checking or replacement of the exhaust muffler of reduced noise emission part no. 979405 for ROTAX engine type 914 F |
| SB-914-016 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 01.11.2002 | n.a. | Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (Series) |
| SB-914-016-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 01.11.2002 | n.a. | Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (series) |
| SB-914-017 | 914 F | 0 | 1 | 01.07.2002 | n.a. | Checking or replacement of exhaust bend on ROTAX engine type 914 (Series) |
| SB-914-017-UL | 914 UL | 0 | 1 | 01.07.2002 | n.a. | Checking or replacement of the exhaust bend on ROTAX engine type 914 (series) |
| SB-914-018 | 912 A, 912 F, 912 S, 914 F | 0 | 3 | 11.07.2006 | n.a. | Checking of crankcase on ROTAX engine type 912 and 914 (Series) |
| SB-914-018-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 3 | 11.07.2006 | n.a. | Checking of the crankcase on ROTAX engine type 912 and 914 (Series) |
| SB-914-019 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 01.02.2004 | n.a. | Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series) |
| SB-914-019-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 01.02.2004 | n.a. | Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series) |
| SB-914-020 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.08.2002 | n.a. | Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914 |
| SB-914-020-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.08.2002 | n.a. | Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914 |
| SB-914-021 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 01.09.2002 | n.a. | Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series) |
| SB-914-021-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 01.09.2002 | n.a. | Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series) |
| SB-914-022 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 23.01.2007 | n.a. | CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040/SB-914-026, latest edition |
| SB-914-022-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 23.01.2007 | n.a. | CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040UL/SB-914-026UL, latest edition |
| SB-914-023 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 01.10.2003 | n.a. | Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie) |
| SB-914-023-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.10.2002 | n.a. | Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie) |
| SB-914-024 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.11.2002 | | CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series) |
| SB-914-024-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.11.2002 | | CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series) |
| SB-914-025 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.12.2002 | | Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series) |
| SB-914-025-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.12.2002 | | Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series) |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|------------------------------------|-------|----------|------------|-------|--|
| SB-914-026 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 01.08.2003 | | Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series) |
| SB-914-026-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.04.2003 | | Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series) |
| SB-914-027 | 912 A, 912 F, 912 S, 914 F | 0 | 2 | 25.03.2010 | | Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series) |
| SB-914-027-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 2 | 25.03.2010 | | Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series) |
| SB-914-028 | 914 F | 0 | 1 | 08.11.2004 | n.a. | Inspection of exhaust muffler part no. 979402 / 979404 for Rotax engine type 914 (Series) |
| SB-914-028-UL | 914 UL | 0 | 1 | 08.11.2004 | n.a. | Inspection of exhaust muffler part no. 979402 / 979404 for Rotax engine type 914 (Series) |
| SB-914-029 | 912 A, 912 F, 912 S, 914 F | 0 | 2 | 10.11.2006 | | Change of coolant specification on ROTAX engine type 912 and 914 (Series) |
| SB-914-029-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 28.08.2006 | | Change of coolant specification on ROTAX engine type 912 and 914 (Series) |
| SB-914-030 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 19.11.2004 | | Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series) |
| SB-914-030-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 19.11.2004 | | Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series) |
| SB-914-031 | 912 S, 914 F | 0 | 0 | 26.07.2005 | | Check of the support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series) |
| SB-914-031-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 26.07.2005 | | Check of support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series) |
| SB-914-032 | 912 S, 914 F | 0 | 0 | 29.07.2005 | | Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series) |
| SB-914-032-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 29.07.2005 | | Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series) |
| SB-914-033 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 23.09.2005 | | Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series) |
| SB-914-033-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 23.09.2005 | | Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series) |
| SB-914-034 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 30.01.2008 | | Checking of magnetic plug on Rotax engine type 912/914 (Series) |
| SB-914-034-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 30.01.2008 | | Checking of magnetic plug on Rotax engine type 912/914 (Series) |
| SB-914-035 | 912 A, 912 F, 912 S, 914 F | 0 | 4 | 13.06.2014 | | Installation / Use of governors for Rotax engine type 912 and 914 |
| SB-914-035-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 3 | 13.06.2014 | | Installation / Use of governors for Rotax engine type 912i, 912 and 914 (Series) |
| SB-914-036 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 31.08.2007 | | Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series) |
| SB-914-036-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 31.08.2007 | | Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series) |
| SB-914-037 | 914 F | 0 | 0 | 20.12.2007 | | Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series) |
| SB-914-037-UL | 914 UL | 0 | 0 | 20.12.2007 | | Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series) |
| SB-914-038 | 912 S, 914 F | 0 | 1 | 05.08.2008 | | Replacement of the propeller gearbox for some Rotax engines type 912/914 (Series) |
| SB-914-038-UL | 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 05.08.2008 | | Replacement of the propeller gearbox for some ROTAX engines type 912/914 (Series) |
| SB-914-039 | 914 F | 0 | 0 | 25.03.2010 | | Extension of time between overhauls (TBO) for ROTAX engine type 914 (Series) |
| SB-914-039-UL | 914 UL | 0 | 0 | 25.03.2010 | | Extension of time between overhauls (TBO) for ROTAX engine type 914 (Series) |
| SB-914-040 | 914 F | 0 | 0 | 10.03.2011 | | Replacement of fuel pressure regulator part no. 887130 for ROTAX engine type 914 (Series) |
| SB-914-040-UL | 914 UL | 0 | 0 | 10.03.2011 | | Replacement of fuel pressure regulator assy. part no. 887130 for ROTAX engine type 914 (Series) |
| SB-914-041 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 15.04.2011 | | Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series) |
| SB-914-041-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 15.04.2011 | | Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series) |
| SB-914-042 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 01.01.2012 | | Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series) |
| SB-914-042-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 0 | 01.01.2012 | | Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series) |
| SB-914-045 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 11.11.2013 | | Periodic checking of the crankshaft journal (power take off side) for ROTAX Engine Type 912 and 914 (Series) |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|--|-------|----------|------------|--------|--|
| SB-914-045-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 11.11.2013 | | Periodic checking of the crankshaft journal (power take off side) for ROTAX Engine Type 912 and 914 (Serie) |
| SB-914-046 | 912 A, 912 F, 912 S, 914 F | 0 | 3 | 26.03.2015 | | Periodic inspection of the float buoyancy for ROTAX Engine Type 912 and 914 (Series) |
| SB-914-046-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 3 | 26.03.2015 | | Periodic inspection of the float buoyancy for ROTAX Engine Type 912 and 914 (Series) |
| SB-914-047 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 23.04.2015 | | Change of Measurement Method from Cylinder Head Temperature to Coolant Temperature for ROTAX® Engine Type 912 and 914 (Series) |
| SB-914-047-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 23.04.2015 | | Change of Measurement Method from Cylinder Head Temperature to Coolant Temperature for ROTAX® Engine Type 912 and 914 (Series) |
| SB-914-048 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 26.03.2015 | | Exchange of floats on ROTAX Engine Type 912 and 914 (Series) |
| SB-914-048-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 1 | 26.03.2015 | | Echange of floats on ROTAX Engine Type 912 and 914 (Series) |
| SB-914-049 | 912 A, 912 F, 912 S, 914 F | 0 | 1 | 09.09.2015 | | Specification/Change of Engine Configuration and/or Type Plate for ROTAX Engine Type 912 and 914 (Series) |
| SB-914-049-UL | 912 UL, 912 ULS, 912 ULSFR, 914 UL | 0 | 2 | 09.09.2015 | | Specification/Change of Engine Configuration and/or Type Plate for ROTAX Engine Type 912 and 914 (Series) |
| SB-914-050 | 914 F | 0 | 0 | 13.05.2015 | | Replacement of the overload clutch of ROTAX® Engine Type 914 (Series) |
| SB-914-050-UL | 914 UL | 0 | 0 | 13.05.2015 | | Replacement of the overload clutch of ROTAX® Engine Type 914 (Series) |
| SI-01-1985 | 377 UL, 447 UL, 462 UL, 503 UL, 532 UL | 0 | 0 | 01.04.1985 | n.a. | UL-Propeller-Gear |
| SI-01-1988 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 532 UL | 0 | 0 | 01.01.1988 | n.a. | Function test of rectifier regulator |
| SI-01-1989 | 503 UL | 0 | 0 | 01.03.1989 | n.a. | Fan drive of engine Type 503 |
| SI-01-1991 | 532 UL, 582 UL | 0 | 0 | 01.02.1991 | n.a. | Rotary valve shaft sealing for ROTAX 532 UL and 582 UL |
| SI-01-1992 | 912 UL | 0 | 0 | 01.07.1992 | 897691 | Engine type 912 UL, ignition unit with resistor spark plug |
| SI-01-1993 | 582 UL | 0 | 0 | 01.01.1993 | n.a. | ROTAX 582 UL DCDI - making of pick-up |
| SI-01-1994 | 912 A, 912 UL | 0 | 0 | 01.01.1994 | 897695 | Electronic-box for ROTAX 912 A + UL |
| SI-01-1995 | 912 UL | 0 | 1 | 01.04.1995 | n.a. | CANCELLED - Ground connection for pick-up wiring, ROTAX engine Series Type 912 UL, superseded by SB-912-007 UL, latest edition |
| SI-01-1998 | 912 UL | 0 | 1 | 01.02.1998 | n.a. | CANCELLED - Fuel pump 996592 (pump with screw fittings) 912 (series), superseded by SB-912-020 UL, latest edition |
| SI-02-1984 | 277 UL | 0 | 0 | 25.01.1984 | n.a. | UL-Propeller-Gear 277 |
| SI-02-1985 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 532 UL | 0 | 0 | 01.05.1985 | n.a. | Increase of ignition voltage on BOSCH contact ignition |
| SI-02-1991 | 503 UL, 582 UL, 618 UL | 0 | 0 | 01.02.1991 | n.a. | Tightening torque increase on 'C' gearboxes for UL-engines. |
| SI-02-1992 | 912 A, 912 UL | 0 | 0 | 01.12.1992 | n.a. | Coolant expansion tank ROTAX 912 |
| SI-02-1993 | 912 UL | 0 | 0 | 01.01.1993 | n.a. | CANCELLED - Overload clutch for Rotax engine 912 UL, superseded by relevant Maintenance Manual, latest edition |
| SI-02-1995 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 2 | 0 | 01.08.1995 | n.a. | Contamination of carburetors, ROTAX-series 912 |
| SI-02-1996 | 912 A, 912 UL | 0 | 0 | 01.02.1996 | n.a. | Rectifier regulator, Rotax Series 912 |
| SI-02-1997 | 912 UL | 0 | 0 | 01.02.1997 | n.a. | Camshaft check on ROTAX engine Type 912 UL (series) |
| SI-02-1998 | 914 F, 914 UL | 0 | 0 | 01.06.1998 | n.a. | CANCELLED - ROTAX engine type 914, check / replacement of the turbo oil pressure line and pipe clamps, superseded by SB-914-007 UL, latest edition |
| SI-03-1985 | 277 UL | 0 | 0 | 01.09.1985 | n.a. | UL-Propeller-Gear 277 |
| SI-03-1989 | 377 UL, 447 UL, 503 UL, 532 UL | 0 | 0 | 01.06.1989 | n.a. | Matching a propeller to ROTAX UL-Engines. |
| SI-03-1991 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.04.1991 | n.a. | Daily and Pre-Flight-Check - Maintenance plan for all ROTAX engines |
| SI-03-1993 | 912 UL | 0 | 0 | 01.02.1993 | n.a. | Ignition unit of ROTAX 912 UL |
| SI-03-1994 | 912 A, 912 UL | 0 | 0 | 01.12.1994 | n.a. | Sensor and gauge for oil pressure indication-ROTAX 912 |
| SI-03-1995 | 912 A, 912 UL | 0 | 0 | 01.02.1995 | n.a. | CANCELLED - Cracks in the carburetor flange, engine series type 912, superseded by SB-912-030/SB-914-019 (+UL), latest edition |
| SI-03-1996 | 462 UL, 532 UL, 582 UL, 618 UL | 0 | 1 | 01.09.1999 | n.a. | Rotary valve shaft seal leakage at Rotax engine type 462 UL / 532 UL / 582 UL and 618 UL |
| SI-03-1997 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 1 | 01.01.1999 | n.a. | CANCELLED - Coolant (antifreeze) mixtures for ROTAX engine type 912/914 (Series) - superseded by relevant Operators Manual, latest edition |
| SI-03-1998 | 912 A, 912 F, 912 S, 912 UL, 914 F, 914 UL | 0 | 1 | 01.02.2004 | n.a. | Engine start at low temperatures at Rotax engine type 912 and 914 (Series) |
| SI-03-1999 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.02.1999 | n.a. | Standardization of the crankcase for ROTAX engines 912 and 914 |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|---|-------|----------|------------|--------|--|
| SI-04-1986 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL | 0 | 0 | 01.09.1986 | n.a. | Possible causes for piston seizures or holes in pistons |
| SI-04-1987 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL | 1 | 0 | 01.05.1990 | n.a. | Ultralight engines-unexpected engine stops |
| SI-04-1989 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL | 0 | 0 | 01.01.1989 | n.a. | Use of tool for cageless piston pin needle bearing |
| SI-04-1990 | 582 UL | 0 | 0 | 01.09.1990 | n.a. | Starter gear - electric starter, magneto side, on engine 582 UL |
| SI-04-1993 | 582 UL | 0 | 0 | 01.09.1993 | n.a. | Crankcase modifications - ROTAX 582 DCDI |
| SI-04-1994 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 912 UL, 914 UL | 0 | 0 | 01.02.1994 | n.a. | Carburetor icing on UL-engines |
| SI-04-1995 | 912 A, 912 F, 912 UL | 0 | 0 | 01.05.1995 | n.a. | Floats with a new shape, engine Series Type 912 |
| SI-04-1997 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 3 | 23.01.2007 | 898135 | CANCELLED - Venting of lubrication system for Rotax engine type 912 and 914 (Series), superseded by SI-912-018/SI-914-020, latest edition |
| SI-04-1998 | 914 F, 914 UL | 0 | 1 | 01.06.1998 | n.a. | CANCELLED - ROTAX engine type 914 F (series) Replacement of the waste gate servo cable, superseded by SB-914-008 UL, latest edition |
| SI-05-1988 | 377 UL, 447 UL, 462 UL, 503 UL, 532 UL | 0 | 0 | 01.04.1990 | n.a. | Gearbox fixation on UL-engines type 377 to 532 UL |
| SI-05-1990 | 503 UL, 582 UL | 0 | 1 | 01.12.1990 | n.a. | Disturbance of tachometer 966 072 for 503 UL C.D.I. and 582 UL with DUCATI ignition unit |
| SI-05-1991 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.12.1991 | n.a. | Piston for ROTAX UL engines (2-stroke) |
| SI-05-1994 | 912 A, 912 UL | 0 | 0 | 01.03.1994 | n.a. | Banjo Bolt ROTAX 912 |
| SI-05-1995 | 912 UL | 0 | 2 | 01.07.1996 | n.a. | External alternator for engine series type 912 UL, Mod. 94 |
| SI-05-1996 | 447 UL, 503 UL | 0 | 0 | 01.03.1997 | n.a. | Cracks in the carburetor socket, ROTAX 447 and 503 UL |
| SI-05-1997 | 912 A, 912 F, 912 UL, 914 F, 914 UL | 0 | 1 | 01.04.1997 | n.a. | Exhaust flange of ROTAX engines 912/914 (series) |
| SI-05-1998 | 914 F, 914 UL | 0 | 0 | 01.06.1998 | n.a. | Acceptable cracks in the turbine housing of the turbo charger for engine 914 |
| SI-05-1999 | 914 UL | 0 | 0 | 01.10.1999 | n.a. | CANCELLED - Turbocharge control unit (TCU) with software level according to RTCA DO 178 B, for ROTAX engine Type 914 F (series), superseded by SB-914-013 UL, latest edition |
| SI-06-1986 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL | 0 | 0 | 01.12.1986 | n.a. | UL-Reduction gear box |
| SI-06-1987 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL | 0 | 0 | 01.07.1987 | n.a. | Engine-Instruments |
| SI-06-1993 | 582 UL | 0 | 0 | 01.09.1993 | n.a. | ROTAX 582 UL carb adapter |
| SI-06-1994 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.07.1994 | n.a. | Incorrect Model fuel pumps without bleed hole, ROTAX 2-cycle engines |
| SI-06-1995 | 912 UL | 0 | 2 | 01.07.1996 | n.a. | External alternator for engine series type 912 UL, Mod. 89 and 91 |
| SI-06-1996 | 503 UL, 582 UL, 618 UL | 0 | 0 | 01.03.1997 | n.a. | Modifications on reduction gearbox 'C' and 'E' |
| SI-06-1997 | 912 A, 912 F, 912 UL, 914 F, 914 UL | 0 | 1 | 18.02.2005 | n.a. | Friction torque check of propeller gear with overload clutch on Rotax engine type 912 and 914 (Series) |
| SI-06-1998 | 447 UL, 503 UL, 532 UL, 582 UL, 618 UL | 0 | 1 | 01.07.2001 | n.a. | Amendment on reduction gearbox type 'C' and type 'E' for 2-stroke UL aircraft engines |
| SI-06-1999 | 912 S, 912 ULS | 0 | 0 | 01.01.1998 | n.a. | ROTAX engine Type 912 ULS/S, Oil consumption |
| SI-07-1987 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL | 1 | 0 | 01.04.1990 | n.a. | Fuel consumption, 2-stroke UL-Engine |
| SI-07-1991 | 447 UL, 508 UL | 0 | 0 | 01.05.1991 | 897550 | Wiring diagr. for 447 UL SCDI and 508 UL SCDI in conj. with electr. tachometer |
| SI-07-1993 | 447 UL | 0 | 0 | 01.09.1993 | n.a. | Revolution counter for ROTAX 447 SCDI |
| SI-07-1994 | 582 UL | 0 | 0 | 01.07.1994 | n.a. | ROTAX 582 UL crankshaft |
| SI-07-1995 | 277 UL, 377 UL, 447 UL, 503 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 1 | 01.02.1999 | n.a. | New airfilter with securing tab |
| SI-07-1996 | 912 UL | 0 | 0 | 01.09.1996 | n.a. | CANCELLED - Replacement of rocker arms on ROTAX 912 UL (series), superseded by SB-912-015 UL, latest edition |
| SI-07-1997 | 914 UL | 0 | 0 | 01.07.1997 | n.a. | CANCELLED - Calibration of the mixture enrichment jet of ROTAX 914 UL (series), superseded by SB-914-003 UL, latest edition |
| SI-07-1998 | 503 UL | 0 | 0 | 12.10.1998 | n.a. | 'B' type gearbox installation, ROTAX 503 UL DCDI (all versions) |
| SI-08-1987 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL | 0 | 0 | 01.06.1990 | n.a. | Influence of ambient air temperature and barometric pressure on engine performance and carb calibration |
| SI-08-1991 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.06.1991 | n.a. | Safety-check of the BING-carburetors used in all ROTAX UL-engines |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|--|-------|----------|------------|--------|--|
| SI-08-1993 | 912 A, 912 UL | 0 | 0 | 01.10.1993 | | CANCELLED - General overhaul of ROTAX 912 A/UL, superseded by SB for TBO Extension, latest edition |
| SI-08-1994 | 582 UL | 0 | 0 | 01.05.1994 | n.a. | Attaching of water pump housing on ROTAX 582 UL |
| SI-08-1995 | 912 UL | 0 | 1 | 01.12.1995 | n.a. | CANCELLED - Fitting of a carburetor support, Rotax Series 912, superseded by SB-912-010 UL, latest edition |
| SI-08-1996 | 618 UL | 0 | 0 | 01.03.1997 | n.a. | Installation of oversize pistons, ROTAX 618 UL |
| SI-08-1998 | 914 UL | 0 | 1 | 01.02.1999 | n.a. | CANCELLED - ROTAX engine series type 914 UL, verification of the wiring harness, superseded by SB-914-012 UL, latest edition |
| SI-08-1999 | 447 UL, 503 UL, 582 UL | 0 | 0 | 01.02.1999 | | CANCELLED - Documentations for 447 - 503 - 582 - 582 Mod. 99, superseded by SL-2ST-002, latest edition |
| SI-09-1991 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.11.1991 | 897701 | Installation Instructions for ROTAX UL-engines |
| SI-09-1993 | 618 UL | 0 | 0 | 01.11.1993 | n.a. | Assembly instructions for ROTAX 618 water pump cover |
| SI-09-1994 | 503 UL, 532 UL, 582 UL, 618 UL | 0 | 2 | 01.01.2004 | 897891 | Installation Instruction of UL reduction gearbox type 'C' and 'CL' |
| SI-09-1996 | 914 UL | 0 | 0 | 01.03.1998 | n.a. | ROTAX 914 UL exchange of the oilpump housing |
| SI-09-1997 | 503 UL | 0 | 0 | 01.07.1997 | n.a. | Exchange of piston pins, ROTAX 503 UL |
| SI-10-1987 | 503 UL | 0 | 0 | 01.11.1987 | n.a. | 503 UL- FREE AIR Version |
| SI-10-1991 | 912 A, 912 UL | 0 | 0 | 01.09.1991 | n.a. | Water distributor for ROTAX 912 A and 912 UL |
| SI-10-1994 | 503 UL, 532 UL, 582 UL, 618 UL | 0 | 2 | 01.01.2004 | 897892 | Installation Instruction of UL reduction gearbox type 'E' and 'EL' |
| SI-10-1996 | 277 UL, 377 UL, 447 UL, 503 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.05.1997 | n.a. | Piston pin circlip installation (2-stroke UL-engines) |
| SI-10-1999 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.03.1999 | n.a. | Illustrated Parts Catalog (IPC) for ROTAX engines 912 / 914 (series) |
| SI-11-1987 | 377 UL, 447 UL, 503 UL, 532 UL | 0 | 0 | 01.11.1987 | n.a. | Exhaust systems for 377/447/462/503/532 |
| SI-11-1991 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.12.1992 | n.a. | Propeller mass moment of inertia |
| SI-11-1994 | 503 UL | 1 | 0 | 01.06.1994 | 897893 | Subsequent install. or retrofit of an oil-Pump for separate oil Lubrication |
| SI-11-1996 | 277 UL, 377 UL, 447 UL, 503 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.01.1998 | n.a. | Engine preservation for 2-stroke- UL- engines |
| SI-11-1997 | 914 F, 914 UL | 0 | 0 | 01.12.1997 | n.a. | Adjustment or verification of the wastegate position on ROTAX 914 |
| SI-12-1991 | 508 UL | 0 | 0 | 01.12.1992 | n.a. | 508 UL-Valve Cover Attachment |
| SI-12-1994 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL | 0 | 2 | 01.01.2004 | 897890 | Installation Instruction of UL reduction gearbox Type 'B' |
| SI-12-1996 | 912 A, 912 F, 912 UL, 914 F, 914 UL | 0 | 0 | 01.12.1996 | n.a. | CANCELLED - Oil filter ROTAX 912 / 914 engine, superseded by SB-912-017/SB-914-037 UL, latest edition |
| SI-12-1997 | 914 F, 914 UL | 0 | 0 | 01.07.1997 | n.a. | CANCELLED - Checking of the banjo bolt in the pressure oil line of turbo charger for ROTAX engine Type 914 (series), superseded by SB-914-004 UL, latest edition |
| SI-13-1994 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.07.1994 | n.a. | Using auto fuel in ROTAX two cycle aircraft engine |
| SI-13-1996 | 912 A, 912 F, 912 UL, 914 F, 914 UL | 0 | 2 | 23.06.2009 | n.a. | Installation instructions of rev-counter part no. 966403 and 966408 for Rotax engine type 912 and 914 (Series) |
| SI-13-1997 | 914 F, 914 UL | 0 | 0 | 01.12.1997 | n.a. | CANCELLED - Introduction of a turbo charger with a modified wastegate on Rotax 914, superseded by SB-914-005 UL, latest edition |
| SI-14-1994 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.07.1994 | n.a. | ROTAX two-cycle aircraft engines crankshaft failures, piston seizures |
| SI-14-1997 | 912 A, 912 F, 912 UL, 914 F, 914 UL | 0 | 1 | 01.03.1998 | n.a. | Introduction of the single valve spring arrangement on Rotax engine type 912 and 914 (series) |
| SI-15-1994 | 447 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.11.1995 | n.a. | Rev. counter for DUCATI ignition unit |
| SI-15-1997 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 2 | 24.11.2010 | n.a. | CANCELLED - Spark plugs for ROTAX engines 912/914 (Series), superseded by Maintenance Manual Line, latest edition |
| SI-16-1997 | 912 A, 912 F, 912 UL, 914 F, 914 UL | 0 | 1 | 01.12.1997 | n.a. | Introduction of a modified oil pressure sensor 912/914 |
| SI-17-1994 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.06.1994 | n.a. | Weight, centre of gravity and moments of inertia of ROTAX UL-engines |
| SI-17-1997 | 277 UL, 377 UL, 447 UL, 503 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.11.1997 | n.a. | Introduction of resistance spark plugs for Rotax 2-stroke engines |
| SI-18-1994 | 912 UL | 1 | 0 | 01.11.1994 | n.a. | Grounding cable for electronic module for ROTAX 912 |
| SI-18-1997 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 5 | 28.08.2006 | n.a. | CANCELLED - Selection of Motor Oil and General Operating Tips for Rotax engines Type 912 and 914 (series), superseded by SI-912-016/SI-914-019 latest edition |
| SI-19-1994 | 582 UL | 0 | 0 | 01.06.1994 | n.a. | Cylinder and Piston for ROTAX 582 DCDI |
| SI-19-1997 | 618 UL | 0 | 0 | 01.12.1997 | n.a. | Version without intake silencer 618 UL |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|--|-------|----------|------------|-------|---|
| SI-20-1994 | 912 A, 912 UL | 0 | 3 | 01.10.1996 | n.a. | Lubrication system for all ROTAX 912 |
| SI-20-1997 | 277 UL, 377 UL, 447 UL, 503 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.11.1997 | n.a. | New flydat configuration for Rotax UL and aircraft engines |
| SI-21-1994 | 912 A, 912 F, 912 S, 912 UL, 912 ULS | 0 | 0 | 01.07.1994 | n.a. | CANCELLED - 912 carburetor fixation, superseded by SB-912-030/SB-914-019 (+UL), latest edition |
| SI-21-1997 | 912 A, 912 F, 912 UL, 914 F, 914 UL | 0 | 1 | 01.11.1998 | n.a. | Introduction of the mono hook circlip at ROTAX 912 and 914 series |
| SI-22-1994 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL | 0 | 0 | 01.12.1994 | n.a. | supply scope of ROTAX crankshafts |
| SI-22-1997 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.11.1997 | n.a. | Pressure oil line for hydraulic governor 912/914 |
| SI-25-1994 | 912 UL | 0 | 0 | 01.11.1994 | | Ensuring of a ground connection between screening box part no. 996 611 and engine |
| SI-25-1997 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 11 | 18.07.2007 | n.a. | CANCELLED - Running modifications on Rotax engine type 912 and 914 (series), superseded by SI-912-020/SI-914-022, latest edition |
| SI-26-1994 | 912 UL | 0 | 0 | 01.11.1994 | n.a. | TBO for ROTAX engine type 912 UL-series |
| SI-26-1997 | 912 UL, 914 UL | 0 | 0 | 01.09.1998 | n.a. | Supplementing the Maintenance Manual in regard to propeller gearbox without overload clutch |
| SI-27-1994 | 912 UL | 1 | 0 | 01.03.1995 | n.a. | Special inspection to increase the TBO for engine type 912 UL |
| SI-27-1997 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 1 | 17.07.2012 | n.a. | CANCELLED - Oil level check for ROTAX engine type 912 and 914 (Series), superseded by relevant Maintenance Manual, latest edition |
| SI-2ST-001 | 582 UL, 618 UL | 0 | 0 | 01.04.1999 | n.a. | Installation instructions for the new design piston for 582 UL with mono hook piston pin circlip grooves |
| SI-2ST-002 | 582 UL, 618 UL | 0 | 0 | 01.05.2000 | n.a. | Change of the exhaust gasket on engine type 582 UL mod. 90/99 und type 618 UL |
| SI-2ST-003 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.08.2001 | | Check of the fuel pressure gauge kit part no. 874 230 for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines |
| SI-2ST-004 | 447 UL, 503 UL, 582 UL, 618 UL | 0 | 1 | 11.07.2006 | | Running modifications on ROTAX 2-stroke UL aircraft engines |
| SI-2ST-005 | 582 UL | 0 | 0 | 01.12.2001 | | Modified rotary valve cover for ROTAX engine type 582 UL (replaced by SB-2ST-002) |
| SI-2ST-006 | 447 UL, 503 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 0 | 0 | 22.12.2006 | | Airfilter for Rotax engine type 912 (Series) and 2-stroke UL aircraft engines |
| SI-2ST-007 | 447 UL, 503 UL, 532 UL, 582 UL, 618 UL | 0 | 2 | 20.05.2008 | | Amendment on reduction gearbox type C and type E for ROTAX 2-stroke UL aircraft engines |
| SI-2ST-008 | 447 UL, 503 UL, 582 UL, 618 UL | 0 | 0 | 08.04.2009 | n.a. | Selection of suitable operating fluids for ROTAX 2-stroke UL engines |
| SI-2ST-009 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 09.11.2009 | n.a. | Inspection of carburetors for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines |
| SI-912-001 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.04.1999 | n.a. | Installation of rotary water pump seal and water pump impeller |
| SI-912-002 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.06.1999 | n.a. | Verification of the Lubrication system and replacement of the oil pressure spring for engine type 912 and 914 |
| SI-912-003 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 2 | 19.03.2009 | n.a. | Oil line connections with UNF-threads (AN-8) for ROTAX engine types 912 and 914 (series) |
| SI-912-004 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.08.1999 | n.a. | CANCELLED - Modified carburetor flange for Rotax engine type 912 (series) and Rotax engine type 914 (series), superseded by SB-912-030/SB-914-019 (+UL), latest edition |
| SI-912-005 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.02.2000 | n.a. | Lubrication system for all ROTAX engine type 912 (series) and 914 (series) |
| SI-912-006 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 03.02.2009 | | Replacement of the circlip in the sprag clutch housing on ROTAX engine type 912 and 914 (series) |
| SI-912-007 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.08.2001 | | Check of the fuel pressure gauge kit part no. 874 230 for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines |
| SI-912-008 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 0 | 1 | 01.02.2002 | | Fuel pressure indication problems on ROTAX engine type 912 (series) |
| SI-912-009 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.10.2001 | | Introduction of a new rocker arm bushing for ROTAX engine type 912 and 914 (series) |
| SI-912-010 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 4 | 02.10.2012 | n.a. | Oil change on Rotax engine type 912i, 912 and 914 (Series) |
| SI-912-011 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.03.2003 | n.a. | Replacement of the gasket rings on the adaptor of the oil radiator for Rotax engine type 912 and 914 (series) |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|--|-------|----------|------------|-------|---|
| SI-912-012 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 1 | 01.03.2004 | n.a. | Routine Modifications of the Bing constant depression carburetor on ROTAX engine type 912 and 914 (Series) |
| SI-912-013 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.04.2004 | n.a. | Standardization of the ignition unit for ROTAX engine type 912 and 914 (Series) |
| SI-912-014 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.06.2004 | n.a. | Optimizing of piston ring position for ROTAX engine type 912 and 914 (Series) |
| SI-912-015 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.06.2004 | | Increase of disk spring pre-tension in the gearbox on ROTAX engine type 912 and 914 (Series) |
| SI-912-016 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 8 | 16.04.2015 | n.a. | Selection of suitable operating fluids for Rotax engine type 912 i, 912 and 914 (Series) |
| SI-912-017 | 447 UL, 503 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 0 | 0 | 22.12.2006 | | Airfilter for Rotax engine type 912 (Series) and 2-stroke UL aircraft engines |
| SI-912-018 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 02.10.2012 | | Purging of lubrication system for Rotax engine type 912i, 912 and 914 (Series) |
| SI-912-019 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 3 | 13.06.2014 | | Oil leakages in the area of the cylinder barrel for Rotax engine type 912i, 912 and 914 (Series) |
| SI-912-020 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 8 | 19.12.2014 | n.a. | Running modifications on ROTAX engine type 912 and 914 (Series) |
| SI-912-021 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 09.11.2009 | n.a. | Inspection of carburetors for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines |
| SI-912-022 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR | 0 | 0 | 20.01.2014 | | Cancellation of the 5-years change interval for fuel hoses (teflon hoses) for ROTAX Engine Type 912 (Series) |
| SI-912-023 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 04.11.2015 | | Introduction of a radiator retrofit kit part no. 881535 for the new radiator part no. 997083 on ROTAX engine type 912i, 912 and 914 (Series) |
| SI-912-024 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 19.11.2015 | | Introduction of new oil radiator/-sets on ROTAX Engine Type 912 i, 912 und 914 (Series) |
| SI-912i-001 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 3 | 16.04.2015 | n.a. | Selection of suitable operating fluids for Rotax engine type 912 i, 912 and 914 (Series) |
| SI-912i-002 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 1 | 13.06.2014 | | B.U.D.S. Aircraft Installation Instructions for ROTAX Engine Type 912 i Series |
| SI-912i-003 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 4 | 13.06.2014 | | B.U.D.S. Aircraft Update for ROTAX Engine Type 912 i Series |
| SI-912i-004 | 912 iS | 0 | 0 | 02.10.2012 | | Purging for lubrication system for Rotax Engine Type 912i Series |
| SI-912i-005 | 912 iS | 0 | 0 | 02.10.2012 | n.a. | Oil change on Rotax engine type 912i, 912 and 914 (Series) |
| SI-912i-006 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 1 | 13.06.2014 | | Oil leakages in the area of the cylinder barrel for Rotax engine type 912i, 912 and 914 (Series) |
| SI-912i-007 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 0 | 04.11.2015 | | Introduction of a radiator retrofit kit part no. 881535 for the new radiator part no. 997083 on ROTAX engine type 912i, 912 and 914 (Series) |
| SI-912i-008 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 0 | 19.11.2015 | | Introduction of new oil radiator/-sets on ROTAX Engine Type 912 i, 912 und 914 (Series) |
| SI-912i-009 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 0 | 21.01.2016 | | Introduction of a new fuel filter part no. 874060 for ROTAX Engine Type 912 iS and 912 iS Sport |
| SI-914-001 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.04.1999 | n.a. | Installation of rotary water pump seal and water pump impeller |
| SI-914-002 | 914 F, 914 UL | 0 | 0 | 01.04.1999 | n.a. | Optimizing of mixture distribution |
| SI-914-003 | 914 F, 914 UL | 0 | 1 | 15.04.2008 | n.a. | Inspection and lubrication of Wastegate for ROTAX engine type 914 (Series) |
| SI-914-004 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.06.1999 | n.a. | Verification of the Lubrication system and replacement of the oil pressure spring for engine type 912 and 914 |
| SI-914-005 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 2 | 19.03.2009 | n.a. | Oil line connections with UNF-threads (AN-8) for ROTAX engine types 912 and 914 (series) |
| SI-914-006 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.08.1999 | n.a. | CANCELLED - Modified carburetor flange for Rotax engine type 912 (series) and Rotax engine type 914 (series), superseded by SB-912-030/SB-914-019 (+UL), latest edition |
| SI-914-007 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.02.2000 | n.a. | Lubrication system for all ROTAX engine type 912 (series) and 914 (series) |
| SI-914-008 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 03.02.2009 | | Replacement of the circlip in the sprag clutch housing on ROTAX engine type 912 and 914 (series) |
| SI-914-009 | 277 UL, 377 UL, 447 UL, 462 UL, 503 UL, 508 UL, 532 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.08.2001 | | Check of the fuel pressure gauge kit part no. 874 230 for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines |
| SI-914-010 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.10.2001 | | Introduction of a new rocker arm bushing for ROTAX engine type 912 and 914 (series) |
| SI-914-011 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 4 | 02.10.2012 | n.a. | Oil change on Rotax engine type 912i, 912 and 914 (Series) |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|--|-------|----------|------------|-------|---|
| SI-914-012 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.03.2003 | n.a. | Replacement of the gasket rings on the adaptor of the oil radiator for Rotax engine type 912 and 914 (series) |
| SI-914-013 | 914 F, 914 UL | 0 | 0 | 01.04.2003 | | Introduction of a new airbox for Rotax engine type 914 (series) |
| SI-914-014 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 1 | 01.03.2004 | n.a. | Routine Modifications of the Bing constant depression carburetor on ROTAX engine type 912 and 914 (Series) |
| SI-914-015 | 914 F, 914 UL | 0 | 0 | 01.12.2003 | | Introduction of a new airbox part no. 667167 for Rotax engine type 914 (Series) |
| SI-914-016 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.04.2004 | n.a. | Standardization of the ignition unit for ROTAX engine type 912 and 914 (Series) |
| SI-914-017 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.06.2004 | n.a. | Optimizing of piston ring position for ROTAX engine type 912 and 914 (Series) |
| SI-914-018 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.06.2004 | | Increase of disk spring pre-tension in the gearbox on ROTAX engine type 912 and 914 (Series) |
| SI-914-019 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 8 | 16.04.2015 | n.a. | Selection of suitable operating fluids for Rotax engine type 912 i, 912 and 914 (Series) |
| SI-914-020 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 02.10.2012 | | Purging of lubrication system for Rotax engine type 912i, 912 and 914 (Series) |
| SI-914-021 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 3 | 13.06.2014 | | Oil leakages in the area of the cylinder barrel for Rotax engine type 912i, 912 and 914 (Series) |
| SI-914-022 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 8 | 19.12.2014 | n.a. | Running modifications on ROTAX engine type 912 and 914 (Series) |
| SI-914-023 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 09.11.2009 | n.a. | Inspection of carburetors for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines |
| SI-914-024 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 04.11.2015 | | Introduction of a radiator retrofit kit part no. 881535 for the new radiator part no. 997083 on ROTAX engine type 912i, 912 and 914 (Series) |
| SI-914-025 | 912 A, 912 F, 912 S, 914 F | 0 | 0 | 19.11.2015 | | Introduction of new oil radiator/-sets on ROTAX Engine Type 912 i, 912 und 914 (Series) |
| SL-2ST-001 | 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 1 | 01.07.1999 | n.a. | Change of desig. of Tech. Bulletins and Service Information in acc. with the new ROTAX standard for ROTAX 2-stroke UL aircraft engines, ROTAX 912 (series) and ROTAX 914 (series) |
| SL-2ST-002 | 277 UL, 377 UL, 447 UL, 462 UL, 501, 503 UL, 505, 505 A, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL | 0 | 1 | 12.01.2005 | n.a. | Documentations for ROTAX 2-stroke UL engines and certified 2-stroke aircraft engines |
| SL-2ST-003 | 185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 2 | 01.07.2000 | n.a. | CANCELLED - List of documentation for ROTAX 2-Stroke Aircraft engines and all versions of engine Type 912 / 914 - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition |
| SL-2ST-004 | 377 UL, 447 UL, 462 UL, 501, 503 UL, 505, 505 A, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.12.1999 | n.a. | Change of layout for: Alert Service Bulletin (ASB), Service Bulletins (SB), Service Instructions (SI) and Service Letters (SL) |
| SL-2ST-005 | 447 UL, 503 UL, 582 UL, 618 UL | 0 | 0 | 01.07.2001 | n.a. | Running modifications on carburetors for ROTAX 2-stroke UL aircraft engines |
| SL-2ST-006 | 447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 2 | 30.03.2009 | n.a. | Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines |
| SL-2ST-007 | 377 UL, 447 UL, 462 UL, 463, 503 UL, 505, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 8 | 24.07.2015 | | List of stolen ROTAX engines type 912 and 914 (Series) and 2-stroke aircraft engines |
| SL-2ST-008 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 5 | 01.09.2014 | | Non-approved modifications or use of ROTAX unapproved engine components or accessories for ROTAX aircraft engines |
| SL-2ST-009 | 447 UL, 503 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 08.03.2012 | | Definition for propeller strike or accidental engine stoppage on ROTAX engine type 912 i, 912 and 914 (Series) and 2-stroke aircraft engines |
| SL-912-001 | 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 1 | 01.07.1999 | n.a. | Change of desig. of Tech. Bulletins and Service Information in acc. with the new ROTAX standard for ROTAX 2-stroke UL aircraft engines, ROTAX 912 (series) and ROTAX 914 (series) |
| SL-912-002 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 2 | 28.05.2010 | n.a. | Standardization of the crankshaft/piston pin and of the gearbox for ROTAX engine type 912/914 (Series) |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|--|-------|----------|------------|-------|---|
| SL-912-003 | 185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 2 | 01.07.2000 | n.a. | CANCELLED - List of documentation for ROTAX 2-Stroke Aircraft engines and all versions of engine Type 912 / 914 - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition |
| SL-912-004 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 2 | 15.04.2008 | n.a. | Documentation for ROTAX engine type 912 and 914 (Series) |
| SL-912-005 | 377 UL, 447 UL, 462 UL, 501, 503 UL, 505, 505 A, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.12.1999 | n.a. | Change of layout for: Alert Service Bulletin (ASB), Service Bulletins (SB), Service Instructions (SI) and Service Letters (SL) |
| SL-912-006 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 1 | 23.07.2014 | n.a. | Use of third party after-market piston kits in Rotax engines type 912 (series) and 914 (series) |
| SL-912-007 | 912 ULSFR | 0 | 1 | 15.03.2011 | | ROTAX engine type 912 ULSFR - version for France |
| SL-912-008 | 912 A, 912 F, 912 S, 912 UL, 912 ULS | 0 | 0 | 20.07.2000 | | CANCELLED - Operators and Maintenance Manual for ROTAX 912 Series - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition |
| SL-912-009 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 01.12.2003 | n.a. | CANCELLED - Coolant for ROTAX engine type 912 and 914 (Series), superseded by SB-912-043/SB-914-029, latest edition |
| SL-912-010 | 912 S, 912 ULS, 912 ULSFR | 0 | 0 | 01.02.2003 | | Identifying abnormal vibrations on aircrafts equipped with Rotax engine type 912 S/ULS/ULSFR |
| SL-912-011 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 02.10.2012 | n.a. | Use of an oil thermostat for Rotax engine type 912i, 912 and 914 (Series) |
| SL-912-012 | 447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 2 | 30.03.2009 | n.a. | Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines |
| SL-912-013 | 377 UL, 447 UL, 462 UL, 463, 503 UL, 505, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 8 | 24.07.2015 | | List of stolen ROTAX engines type 912 and 914 (Series) and 2-stroke aircraft engines |
| SL-912-014 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 5 | 01.09.2014 | | Non-approved modifications or use of ROTAX unapproved engine components or accessories for ROTAX aircraft engines |
| SL-912-015 | 447 UL, 503 UL, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 08.03.2012 | | Definition for propeller strike or accidental engine stoppage on ROTAX engine type 912 i, 912 and 914 (Series) and 2-stroke aircraft engines |
| SL-912-016 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 28.07.2009 | n.a. | Essential information regarding engine behavior, performance and manifold pressure data for ROTAX engines type 912 und 914 (Series) |
| SL-912-017 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 0 | 01.11.2013 | | Conditions relating to the Limited Extended Warranty for ROTAX Engine Types 912/914 Series and 912 i Series |
| SL-912i-001 | 912 iS | 0 | 0 | 08.03.2012 | | Definition for propeller strike or accidental engine stoppage on ROTAX engine type 912 i, 912 and 914 (Series) and 2-stroke aircraft engines |
| SL-912i-002 | 912 iS | 0 | 0 | 02.10.2012 | n.a. | Use of an oil thermostat for Rotax engine type 912i, 912 und 914 (Series) |
| SL-912i-003 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 0 | 08.03.2012 | | Warranty conditions for ROTAX 912 i Series |
| SL-912i-003 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 1 | 13.06.2014 | | Warranty conditions for ROTAX 912 i Series |
| SL-912i-004 | 912 iS | 0 | 0 | 01.11.2013 | | Conditions relating to the Limited Extended Warranty for ROTAX Engine Types 912/914 Series and 912 i Series |
| SL-912i-005 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 1 | 01.09.2014 | | Non-approved modifications or use of ROTAX unapproved engine components or accessories for ROTAX aircraft engines |
| SL-912i-006 | 912 iS, 912 iS Sport, 912 iSc Sport | 0 | 0 | 23.07.2014 | | Use of third party after-market piston kits in Rotax engines type 912 (series) and 914 (series) |
| SL-914-001 | 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 1 | 01.07.1999 | n.a. | Change of desig. of Tech. Bulletins and Service Information in acc. with the new ROTAX standard for ROTAX 2-stroke UL aircraft engines, ROTAX 912 (series) and ROTAX 914 (series) |
| SL-914-002 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 2 | 28.05.2010 | n.a. | Standardization of the crankshaft/piston pin and of the gearbox for ROTAX engine type 912/914 (Series) |
| SL-914-003 | 185, 275, 277 UL, 377 UL, 447 UL, 462 UL, 463, 501, 503 UL, 505, 505 A, 508 UL, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 2 | 01.07.2000 | n.a. | CANCELLED - List of documentation for ROTAX 2-Stroke Aircraft engines and all versions of engine Type 912 / 914 - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition |
| SL-914-004 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 2 | 15.04.2008 | n.a. | Documentation for ROTAX engine type 912 and 914 (Series) |

| Document Type | Engine Type | Issue | Revision | Date | P.no. | Title |
|---------------|---|-------|----------|------------|-------|---|
| SL-914-005 | 377 UL, 447 UL, 462 UL, 501, 503 UL, 505, 505 A, 532 UL, 535 A, 535 B, 535 C, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 0 | 01.12.1999 | n.a. | Change of layout for: Alert Service Bulletin (ASB), Service Bulletins (SB), Service Instructions (SI) and Service Letters (SL) |
| SL-914-006 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 914 F, 914 UL | 0 | 1 | 23.07.2014 | n.a. | Use of third party after-market piston kits in Rotax engines type 912 (series) and 914 (series) |
| SL-914-007 | 914 F, 914 UL | 0 | 0 | 01.07.2000 | | CANCELLED - Operators and Maintenance Manual for ROTAX 914 Series - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition |
| SL-914-008 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 01.12.2003 | n.a. | CANCELLED - Coolant for ROTAX engine type 912 and 914 (Series), superseded by SB-912-043/SB-914-029, latest edition |
| SL-914-009 | 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 1 | 02.10.2012 | n.a. | Use of an oil thermostat for Rotax engine type 912i, 912 and 914 (Series) |
| SL-914-010 | 447 UL, 503 UL, 582 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 2 | 30.03.2009 | n.a. | Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines |
| SL-914-011 | 377 UL, 447 UL, 462 UL, 463, 503 UL, 505, 582 UL, 618 UL, 912 A, 912 F, 912 S, 912 UL, 912 ULS, 912 ULSFR, 914 F, 914 UL | 0 | 8 | 24.07.2015 | | List of stolen ROTAX engines type 912 and 914 (Series) and 2-stroke aircraft engines |