

# SERVICE LETTER

## LIST OF DOCUMENTATION FOR ROTAX® 2-STROKE AIRCRAFT ENGINES AND ALL VERSIONS OF ENGINE TYPE 912/914

**SL-912-003**

**SL-914-003**

**SL-2ST-003**

### Repeating symbols:

Please, pay attention to the following symbols throughout the Service Bulletin emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **ATTENTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.

### 1) Planning information

#### 1.1) Engines affected

All versions of the engine type:

all 2-stroke UL aircraft engines (Series/pre-series)

all 2-stroke certified aircraft engines (Series/pre-series)

912 (Series/pre-series)

914 (Series/pre-series)

#### 1.2) Concurrent ASB/SB/SI und SL

none

#### 1.3) Reason

|| List of valid documentation according to FAR 21.61 "Instruction for continued airworthiness"

#### 1.4) Subject

List of documentation for ROTAX® 2-stroke aircraft engines and for all versions of ROTAX® engine type 912/914.

#### 1.5) Compliance

RECOMMENDED

For technical reasons we strongly advise to update the documentation to the latest revision in accordance with the enclosed list in the Appendix 4.

#### 1.6) Approval

not required

AUFGEHOBEN (ersetzt durch SB-2ST-000/912-000/914-000 letztgültige Ausgabe)  
CANCELLED (superseded by SB-2ST-000/912-000/914-000 latest edition)