ROTA AIRCRAFT ENGINES SERVICE LETTER

4 SERIES **OPERATORS AND MAINTENANCE MANUAL FOR ROTAX** SL-914-007

Repeating symbols:

- Repeating symbols:
 Please, pay attention to the following symbols throughout the Service Bulletin exphasizing particular information.
 WARNING: Identifies an instruction, which if not followed, may cause servers injustor even death.
 ATTENTION:Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
 NOTE: Information
 1.1) Engines affected

 All versions of the engine type:
 914 (Series/pre-series)

 1.2) Concurrent ASB/SB/SI und SL none

1) Planning information

engine type ROTAX_914 (Manuals of each engine type have ual bas been revised. or PRIFAX_type 914 Series we say gly advise to update the documentation to the latest revision. Upon turbo control unit (TCU) with software velocities of the engine type ROTAX_® 914 (series) and in view of necessary updating and standardization to Operator's Manuals of each engine type have been combined into one Operator's Manual and the Mainter oce Manual has been revised.

JULY 2000 Initial issue

Copyright - ROTAX_® GmbH

d03060