

# SERVICE BULLETIN

## INSPECTION OF THE OIL FILTER

### PART NO. 825701

### FOR ROTAX<sup>®</sup> ENGINE TYPE 912 AND 914 (SERIES)

### SB-912-045UL

### SB-914-030UL

## **MANDATORY**

### Repeating symbols:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.

■ **CAUTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.

◆ **NOTE:** Information useful for better handling.

### 1) Planning information

#### 1.1) Engines affected

All versions of the engine type:

- 914 UL from S/N 4,418.793 to S/N 4,418.841
- 912 UL from S/N 4,406.458 to S/N 4,406.522
- 912 ULS from S/N 5,643.838 to S/N 5,643.932
- 912 ULSFR from S/N 4,430.002 to S/N 4,430.031

Also affected, are all engines equipped with oil filter part no. 825701, shipped from ROTAX<sup>®</sup> as a spare part between July 8<sup>th</sup> 2004 to October 07<sup>th</sup> 2004 at maintenance event.

For complete instructions and compliance to this service bulletin refer to Service Bulletin SB-912-045/SB-914-030, latest edition section 1.2 onward.

- ◆ **NOTE:** Section 1.6) Approval: Is not required for engines of the type UL (series).  
Section 3) Accomplishment: In addition: persons with adequate type-specific training.