



# SERVICE BULLETIN

## INSPECTION OF THE PROPELLER GEARBOX WHEN USING LEADED FUEL FOR ROTAX® ENGINE TYPE 912/914

SB-912-033UL

SB-914-020UL

### **MANDATORY**

#### Repeating symbols:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

- ▲ **WARNING:** Identifies an instruction, which if not followed, may cause serious injury or even death.
- **CAUTION:** Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.
- ◆ **NOTE:** Information useful for better handling.

#### 1) Planning information

##### 1.1) Engines affected

All gearbox of the engine type:

- 912UL3
- 912ULS3
- 912ULSFR3
- 914UL3

If the engines have been run more than 30 % of the complete period of operation on leaded fuel (e.g. AVGAS 100L).

For complete instructions and compliance to this service bulletin refer to

Service Bulletin SB-912-033 and SB-914-020, latest edition section 1.2 onward.

- ◆ **NOTE:** Section 1.6) Approval: Is not required for engines of the type UL (series).  
Section 3) Accomplishment: In addition: persons with adequate type-specific training.