

SB-912 i-000R11
SB-915 i-000
SB-912-000R23
SB-914-000R23
SB-505-000R3
SB-535-000R3

ROTAX
AIRCRAFT ENGINES



This SB revises SB-505-000/SB-535-000/SB-912 i-000R11
SB-912-000/SB-914-000R22, SB-505-000/SB-535-000R3
- dated 04 September 2017

SERVICE BULLETIN

Publication Index for ROTAX® Aircraft Engines

ATA System: 00-00-00 GENERAL NOTE

MANDATORY

1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods and prevailing legal regulations.

BRP-Rotax GmbH & Co KG, cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

1.1) Applicability

All engines of type:

Engine type	Serial number
912 A	(Series / Pre-series)
912 F	(Series / Pre-series)
912 S	(Series / Pre-series)
912 iSc Sport	(Series / Pre-series)
915 iSc A	(Series / Pre-series)
915 iSc B	(Series / Pre-series)
914 F	(Series / Pre-series)
505	(Series / Pre-series)
505 A	(Series / Pre-series)
535 A	(Series / Pre-series)
535 B	(Series / Pre-series)
535 C	(Series / Pre-series)

1.2) Concurrent ASB/SB/SI and SL

none

1.3) Reason

List of valid documentation in accordance with Part 21A.57 "Instruction for continued airworthiness".

1.4) Subject

Publication Index for ROTAX® Aircraft Engines.

d06572.fm

31 January 2018

Current valid documentation see:
www.FLYROTAX.com

00-00-00
Page 1 of 2