

### SERVICE BULLETIN

# Software Update for Engine Control Unit (ECU) on ROTAX<sub>®</sub> Engine Type 915 i (Series)

ATA System: 76-00-00 Engine control

## MANDATORY

### 1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods in accordance with prevailing legal regulations.

BRP-Rotax GmbH & Co KG cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

#### 1.1) Applicability

All versions of  $ROTAX_{\mathbb{R}}$  engines types:

ſ	Engine type	Serial number
	915 iS A	from S/N 9132042 up to S/N 9132182 inclusive

NOTE:

Engines with serial numbers higher than the engines mentioned above have already been equipped with the latest version of ECU software. For relevant information, see the maintenance records and/or the logbook.

Engine type	New ECU part number
915 iS A	864354

NOTE: Engines which have had the ECU replaced with the above part numbers during maintenance or overhaul are equipped with the latest version of ECU software.

For complete instructions and compliance to this Service Bulletin refer to Service Bulletin SB-915 i A-002 / SB-915 i B-002, latest edition section 1.2 onward.

NOTE: Section 1.6) Approval: Is not required for engines of the type iS (Series). Section 3) Accomplishment: In addition: persons with adequate type-specific training.

**Symbols used** For meaning of the symbols used in this document, see chapter >Safety< of the latest Operators Manual for the respective engine type.