

Inspection and/or installation of lock washer A6 for ROTAX® Engine Type 915 i A (Series) and 912 i (Series)

ATA System: 24-20-00 Ignition housing

MANDATORY

1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods in accordance with prevailing legal regulations.

BRP-Rotax GmbH & Co KG cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

1.1) Applicability

All versions of ROTAX® engine types 915 i A and 912 i Sport Series are affected:

Engine type	Serial number
915 iS A	from S/N 9133441 up to S/N 9133444 inclusive from S/N 9133447 up to S/N 9133458 inclusive / S/N 9133460
912 iS Sport	from S/N 7705792 up to S/N 7705808 inclusive from S/N 7705810 up to S/N 7705821 inclusive from S/N 7705823 up to S/N 7705824 inclusive / S/N 7705832

NOTE: On engines with S/N higher than those listed above, inspection have already been completed during serial production.

For complete instructions and compliance to this Service Bulletin refer to Service Bulletin-SB-915 i-009 / SB-912 i-012, latest edition section 1.2 onward.

NOTE: Section 1.6) Approval: Is not required for engines of the type UL, iS (Series).
Section 3) Accomplishment: In addition: persons with adequate type-specific training.

Symbols used For meaning of the symbols used in this document, see chapter >Safety< of the latest Operators Manual for the respective engine type.

Translation into other languages might be performed in the course of language localization but does not lie within ROTAX' scope of responsibility.

In any case the original text in English language and the metric units are authoritative.

d06904.fm