

SERVICE BULLETIN

Replacement of oil pump housing for ROTAX® Engine Type 915 i A and 915 i B (Series)

ATA System: 79-20-00 Oil pump assy.

MANDATORY

1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods in accordance with prevailing legal regulations.

BRP-Rotax GmbH & Co KG cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

1.1) Applicability

All versions of ROTAX® engine types:

Engine type	Serial number
915 iS A	from S/N 9132001 up to S/N 9132239 inclusive

All oil pump housings with part no. 812192 which are stocked as a spare part are also affected and need replacement by part no. 812193.

NOTE: Engine with S/N higher than the range listed above, have new oil pump housing installed during serial production.

For complete instructions and compliance to this Service Bulletin refer to Service Bulletin - SB-915 i A-004 / SB-915 i B-004, latest edition section 1.2 onward.

NOTE: Section 1.6) Approval: Is not required for engines of the type UL, iS (Series).
Section 3) Accomplishment: In addition: persons with adequate type-specific training.

Symbols used For meaning of the symbols used in this document, see chapter >Safety< of the latest Operators Manual for the respective engine type.

Translation into other languages might be performed in the course of language localization but does not lie within ROTAX® scope of responsibility.

In any case the original text in English language and the metric units are authoritative.