



SERVICE INSTRUCTION

B.U.D.S. Aircraft Update for ROTAX® Engine Type 912 i Series

This SI revises SI-912 i-003R3 dated 30. April 2014.

ATA System: 76-00-00

Symbols used:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

General note



Identifies an instruction which, if not followed, may cause serious injury or even fatal injury.



Identifies an instruction which, if not followed, may cause minor or moderate injury.



Denotes an instruction which if not followed, may severely damage the engine or could lead to suspension of warranty.



ENVIRONMENTAL NOTE

Environmental notes give you tips on environmentally conscious behaviour.

NOTE: Information useful for better handling.

A revision bar outside of the page margin indicates a change to text or graphic.

1) Planning information

1.1) Applicability

All versions of the Engine type:

Engine type	Serial number
912 i Series	All

NOTE: All "BRP Utility and Diagnostic Software (B.U.D.S.) Aircraft" versions must be used on a specific engine range only. Refer to the relevant Service Instruction to identify the B.U.D.S. Aircraft version to use with a specific engine type, ECU hardware and ECU software.

1.2) Concurrent ASB/SB/SI and SL

In addition to this Instruction the following Service Instruction must be observed and complied with:

-SI-912 i-002, "B.U.D.S. Aircraft Installation Instructions", current issue.

CANCELLED (superseded by SI-912 i-002/SI-915 i-002, latest edition)

d05795.fm