

## ALERT SERVICE BULLETIN

# Inspection and/or replacement of fuel pump assy. for ROTAX® Engine Type 912 i and 915 i A (Series)

ATA System: 73-10-00 Fuel system

## MANDATORY

### 1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods in accordance with prevailing legal regulations.

BRP-Rotax GmbH & Co KG cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

#### 1.1) Applicability

**NOTE:** Make sure to check the whole set of criteria mentioned in this section.

All versions of ROTAX® engine types 912 i and 915 i A Series and/or accessory/spare parts are affected, if at least one of the following criteria applies:

If they are delivered with genuine ROTAX® accessory fuel pump assy. part no. 889697 (UNF, packaged) or 889699 (METRIC, packaged), which includes part no. 889696 (UNF) and 889698 (METRIC) with serial numbers listed within Criterion A).

**Criterion A) Fuel pump assy.:**

Fuel pump assy.	Serial number
Part no. 889696	from S/N 180500 up to S/N 189999 inclusive
Part no. 889698	from S/N 180500 up to S/N 189999 inclusive

**NOTE:** Fuel pump assemblies with S/N lower or higher than the range listed above are not affected.

**Criterion B) Engine serial number:**

Engine type	Serial number
912 iS Sport	S/N 7704529, S/N 7704548, from S/N 7704550 up to S/N 7704553 inclusive, from S/N 7704556 up to S/N 7704710 inclusive, from S/N 7704713 up to S/N 7704714 inclusive, S/N 7704717, from S/N 7704719 up to S/N 7704720 inclusive, from S/N 7704722 up to S/N 7704729 inclusive, S/N 7704773
915 iS A	from S/N 9132200 up to S/N 9132218 inclusive, from S/N 9132223 up to S/N 9132239 inclusive, S/N 9132280

If they are provided as a possible accessory in the scope of engine supply with the genuine ROTAX® fuel pump assy. part no. 889697 (UNF, packaged) or 889699 (METRIC, packaged), which includes part no. 889696 (UNF) and 889698 (METRIC) with serial numbers listed within Criterion A).

d06722.fm

## ALERT SERVICE BULLETIN

---

**NOTE:** Engines with S/N higher than the range listed before, have no or a new fuel pump assy. provided as a possible/optional accessory in the scope of engine supply during serial production. See Criterion C).

**Criterion C) Spare parts:**

Further all engines are affected, which are installed in combination with fuel pump assy. part no. 889697 (UNF, packaged) or 889699 (METRIC, packaged), which includes part no. 889696 (UNF) and 889698 (METRIC) with serial numbers listed within Criterion A) above during engine, repair, maintenance or general overhaul or any other exchange action.

For complete instructions and compliance to this Alert Service Bulletin refer to Alert Service Bulletin - ASB-912 i-010/ASB-915 i A-006, latest edition section 1.2 onward.

**NOTE:** Section 1.6) Approval: Is not required for engines of the type iS (Series). Chapter 3) Accomplishment: In addition: persons with adequate type-specific training.

**Symbols used** For meaning of the symbols used in this document, see chapter >Safety< of the latest Operators Manual for the respective engine type.

Translation into other languages might be performed in the course of language localization but does not lie within ROTAX' scope of responsibility.

In any case the original text in English language and the metric units are authoritative.