



SERVICE BULLETIN

Publication Index for ROTAX Aircraft Engines

ATA System: 00-00-00 GENERAL NOTE

MANDATORY

1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods in accordance with prevailing legal regulations.

BRP-Rotax GmbH & Co KG cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

1.1) Applicability

All versions of ROTAX® engines types:

Engine type	Serial number
2-stroke UL aircraft engines	(Series / Pre-series)
912 UL	(Series / pre-series)
912 ULS	(Series / pre-series)
912 iS	(Series / pre-series)
912 iS Sport	(Series / pre-series)
914 UL	(Series / pre-series)

For complete instructions and compliance with this Service Bulletin refer to Service Bulletin SB-505-000/SB-535-000/SB-912-000/SB-912 i-000/SB-914-000, latest edition, section 1.2 onward.

NOTE: Section 1.6) Approval: Is not required for engines of the type UL, iS (Series).

Translation into other languages might be performed in the course of language localization but does not lie within ROTAX® scope of responsibility.

In any case the original text in English language and the metric units are authoritative.

Symbols used

For meaning of the symbols used in this document, see chapter >Safety< of the latest Operators Manual for the respective engine type.



SERVICE BULLETIN

Publication Index for ROTAX® Aircraft Engines

ATA System: 00-00-00 GENERAL NOTE

MANDATORY

1) Planning information

To obtain satisfactory results, procedures specified in this publication must be accomplished with accepted methods and prevailing legal regulations.

BRP-Rotax GmbH & Co KG. cannot accept any responsibility for the quality of work performed in accomplishing the requirements of this publication.

1.1) Applicability

All engines of type:

Engine type	Serial number
912 A	(Series / Pre-series)
912 F	(Series / Pre-series)
912 S	(Series / Pre-series)
912 iSc Sport	(Series / Pre-series)
914 F	(Series / Pre-series)
505	(Series / Pre-series)
505 A	(Series / Pre-series)
535 A	(Series / Pre-series)
535 B	(Series / Pre-series)
535 C	(Series / Pre-series)

1.2) Concurrent ASB/SB/SI and SL

none

1.3) Reason

List of valid documentation in accordance with Part 21A.57 "Instruction for continued airworthiness".

1.4) Subject

Publication Index for ROTAX® Aircraft Engines.

SERVICE BULLETIN

1.5) Compliance

MANDATORY

For continued airworthiness keep the documentation to the latest valid revision level in accordance with the list attached and the information on the ROTAX® AIRCRAFT ENGINES homepage.



Non-compliance with these instructions could result in engine damages, personal injuries or death!

1.6) Approval

The technical content of this document is approved under the authority of DOA ref. EASA.21J.048.

2) Material Information

none

3) Accomplishment / Instructions

Incorporation / exchange of relevant documentation.

3.1) Enquiries

The following table (list of effective documentation, issue 2017.02.17, page 1-19) includes all the valid documentation for the engine types described in section 1.1).

NOTE: Because of the multitude of documentation a continual updating of the tables is not possible. This Service Bulletin, however, will be updated/revised twice a year. The current documentation (current issue) or relevant revisions (replacement pages) are available at any ROTAX® authorized distributor or their independent Service Centers in printed version or on the ROTAX® AIRCRAFT ENGINES homepage www.FLYROTAX.com (in subsection >Services >Technical Documentation) in electronic and current version.

Symbols used For meaning of the symbols used in this document, see chapter >Safety< in latest Operators Manual of the respective engine type.

Translation into other languages might be performed in the course of language localization but does not lie within ROTAX® scope of responsibility.

In any case the original text in English language and the metric units are authoritative.

Publication Index for ROTAX 2-stroke aircraft engines and all versions of ROTAX aircraft engines type 912 / 912 i / 914

ROTAX
AIRCRAFT ENGINES



Document Type	Engine Type	Issue	Revision	Date	Title
ASB-2ST-003,ASB-914-051UL,ASB-912-069UL	582 UL,914 UL,912 ULS,912 UL	0	1	22.07.2016	Exchange of floats on ROTAX Engine Type 912, 914 and 2-stroke (Series)
ASB-912-053	912 S,912 F,912 A	0	0	20.02.2007	Replacement of fuel pump for Rotax engine type 912 (Series) - replaced by SB-912-053, latest edition
ASB-912-053-UL	912 ULS,912 UL	0	0	20.02.2007	Replacement of fuel pump for Rotax engine type 912 (Series) - replaced by SB-912-053 UL, latest edition
ASB-912-061	912 S,912 F,912 A	0	1	31.05.2012	Replacement of the pressure side fuel hose at fuel pump part no. 893114 for ROTAX engine type 912 (Series)
ASB-912-061-UL	912 ULS,912 UL	0	1	31.05.2012	Replacement of the pressure side fuel hose at fuel pump part no. 893114 for ROTAX engine type 912 (Series)
ASB-912i-005-iS	912 iS SPORT,912 iS	0	0	29.05.2015	The use of lithium-ion batteries in combination with the ROTAX engine type 912 i Series
ASB-914-034,ASB-912-051	914 F,912 S,912 F,912 A	0	0	13.10.2006	CANCELLED - Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition
ASB-914-034-UL,ASB-912-051-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	13.10.2006	CANCELLED - Checking of magnetic plug on Rotax engine type 912/914 (Series), replaced by SB-912-051/SB-914-034, latest edition
ASB-914-042,ASB-912-059	914 F,912 S,912 F,912 A	0	0	01.01.2012	CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059/SB-914-042 latest edition
ASB-914-042-UL,ASB-912-059-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	01.01.2012	CANCELLED - Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series), replaced by SB-912-059UL/SB-914-042UL latest edition
ASB-914-043,ASB-912-060	914 F,912 S	0	0	26.01.2012	Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series)
ASB-914-043-UL,ASB-912-060-UL	914 UL,912 ULS,912 UL	0	0	26.01.2012	Checking of the oil pump fixing bolts for correct torque for ROTAX engine type 912 and 914 (Series)
ASB-914-044,ASB-912-062	914 F,912 S,912 F,912 A	0	2	29.05.2013	Checking of the cylinder head assy. 2/3 for ROTAX engine type 912 and 914 (Series)
ASB-914-044-UL,ASB-912-062-UL	914 UL,912 ULS,912 UL	0	2	29.05.2013	Checking of the cylinder head assy. 2/3 for ROTAX engine type 912 and 914 (Series)
ASB-914-051,ASB-912-069	914 F,912 S,912 F,912 A	0	1	22.07.2016	Exchange of floats on ROTAX Engine Type 912 and 914 (Series)
DIV-912 i	912 iS SPORT,912 iS,912 iSc SPORT	-	-	23.06.2016	B.U.D.S. Log Viewer (Windows) (only available for authorized distributors and overhaul facilities)
DIV-912 i	912 iS SPORT,912 iSc SPORT,912 iS	-	-	23.06.2016	B.U.D.S. Log Viewer (Linux) (only available for authorized distributors and overhaul facilities)
DIV-912 i	912 iS SPORT,912 iSc SPORT,912 iS	-	-	23.06.2016	B.U.D.S. Log Viewer (MacOs) (only available for authorized distributors and overhaul facilities)
DIV-912 i	912 iS SPORT,912 iSc SPORT,912 iS,912 iS	0	3	20.01.2014	BRP Utility and Diagnostic Software B.U.D.S. Aircraft V2.4 (Requires ROTAX USB-to-CAN activation dongle. See SI-912i-002.)

Document Type	Engine Type	Issue	Revision	Date	Title
DIV-914	914 UL,914 F	0	0	01.01.2001	Monitoring-Programm TLR 4.6a
DIV-914	914 UL,914 F	0	0	01.01.2001	Monitoring-Programm TLR 4.3a
DIV-914	914 UL,914 F	0	0	01.01.2001	Monitoring-Programm TLR 4.5a
DIV-914,DIV-912,DIV-2ST	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,642,618 UL,582 UL,535 C,535 B,535 A,532 UL,508 UL,505 A,505,503 UL,501,463,462 UL,447 UL,377 UL,277 UL,275,185	0	2	13.02.2017	Customer Service Information Report
DIV-914,DIV-912,DIV-912i,DIV-2ST	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 iSc SPORT,912 iS SPORT,912 iS,912 F,912 A,642,618 UL,582 UL,535 C,535 B,535 A,532 UL,508 UL,505 A,505,503 UL,501,463,462 UL,447 UL,377 UL,277 UL,275,185	4	0	24.02.2017	ROTAX Aircraft Engine Registration Card
HB-505	505 A	2	0	29.01.1992	Operators manual 505 A without decompressor
IM-505	505 A	1	1	01.07.1988	Installation Manual 501/505 Series (not available - use german version)
IM-535	535 C,535 B,535 A	1	1	01.12.1982	Installation Manual 535 (Series) - (not available - use german version)
IM-582,IM-503,IM-447	582 UL,503 UL,447 UL	0	0	01.05.1999	Installation Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99
IM-912	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	2	1	01.02.2015	Installation Manual ROTAX 912 Series
IM-912	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	2	1	01.02.2015	Revision Pages for Installation Manual ROTAX 912 Series, Issue 2, Revision 1
IM-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	3	01.08.2015	Installation Manual ROTAX 912 i Series, Rev. 3
IM-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	3	01.08.2015	Revision pages for Installation Manual ROTAX 912 i Series, Rev. 3
IM-914	914 UL,914 F	2	1	01.02.2015	Installation Manual 914 Series
IM-914	914 UL,914 F	2	1	01.02.2015	Revision Pages for Installation Manual 914 Series
IPC-277	277 UL	0	2	01.07.1993	Spare Parts List for Engine 277 UL (Nr. 491)
IPC-505	505 A	1	1	01.07.1993	Spare parts list for Engine Type 505A (Nr. 805)
IPC-505	505 A,505	0	0	01.09.1990	Spare Parts List for Engine Type 505/505A (Nr. 744)
IPC-535	535 C	0	0	01.04.1988	Illustrated Parts Catalog 535 C (Nr. 645)
IPC-535	535 B,535 A	0	0	01.07.1983	Illustrated Parts Catalog 535 A and 535 B (No. 448)
IPC-618,IPC-582,IPC-503,IPC-447	618 UL,582 UL,503 UL,447 UL	3	1	01.04.2011	Illustrated parts catalog for ROTAX 447 SCDI, 503 DCDI, 582 DCDI mod. 90, 582 DCDI mod. 99, 618 DCDI
IPC-912	912 UL	0	1	01.11.1994	Illustrated Parts Catalog 912 UL (No. 825)
IPC-912	912 A,912 UL	0	3	01.07.1992	Illustrated parts catalog 912A/912 UL (No. 825)
IPC-912i	912 iSc SPORT,912 iS SPORT,912 iS	3	0	27.01.2017	Illustrated Parts Catalog for ROTAX Engine Type 912 i Series

Document Type	Engine Type	Issue	Revision	Date	Title
IPC-914,IPC-912	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	3	2	01.02.2016	Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL
IPC-914,IPC-912	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	3	2	01.02.2016	Exchange pages for Illustrated parts catalog ROTAX 912 A/F/S/UL/ULS/ULSFR and 914 F/UL, Edition 3, Revision 2
MM-582,MM-503,MM-447	582 UL,503 UL,447 UL	0	0	01.05.1999	Maintenance Manual 447 UL SCDI-503 UL DCDI-582 UL DCDI-582 UL DCDI mod.99
MMH-912,MMH-914	912 F,912 A,914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S	1	4	01.02.2015	Revision Pages for Maintenance Manual (Heavy) for ROTAX 912 and 914 Series, Rev. 4
MMH-912,MMH-914	912 F,912 A,914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S	1	4	01.02.2015	Maintenance Manual (Heavy) for ROTAX 912 and 914 Series
MMH-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	2	01.09.2014	Revision pages for Maintenance Manual Heavy for ROTAX 912 i Series
MMH-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	2	01.09.2014	Maintenance Manual (Heavy) for ROTAX 912 i Series
MML-912	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	3	2	01.02.2015	Revision Pages for Maintenance Manual 912 Series (Line Maintenance), Revision 2
MML-912	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	3	2	01.02.2015	Maintenance Manual 912 Series (Line Maintenance)
MML-912i	912 iSc SPORT,912 iS SPORT,912 iS	0	2	01.06.2014	Revision pages for Maintenance Manual (Line) for ROTAX 912 i Series, Rev. 2
MML-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	2	01.06.2014	Maintenance Manual (Line) ROTAX 912 i Series
MML-914	914 UL,914 F	2	2	01.02.2015	Revision Pages for Maintenance Manual (Line) for 914 Series
MML-914	914 UL,914 F	2	2	01.02.2015	Maintenance Manual (Line) for ROTAX 914 Series
OHM-912i	912 iS SPORT,912 iSc SPORT,912 iSc,912 iS	1	0	01.04.2014	Overhaul Manual 912 i Series (only available for authorized distributors and overhaul facilities)
OHM-914,OHM-912	914 UL,914 F,912 ULS,912 UL,912 F,912 A,912 S	2	3	01.04.2015	Overhaul Manual 912 and 914 Series (only available for authorized distributors and overhaul facilities)
OHMA-912i	912 iS SPORT,912 iSc SPORT,912 iSc,912 iS	1	1	01.04.2014	Appendix to Overhaul Manual 912 i Series (only available for authorized distributors and overhaul facilities)
OHMA-914,OHMA-912	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	1	5	01.03.2016	Appendix to Overhaul Manual 912 and 914 Series (only available for authorized distributors and overhaul facilities)
OM-277	277 UL	0	4	01.03.1988	Operators manual 277 UL
OM-503,OM-447	503 UL,447 UL	19	0	01.06.1994	Operators Manual 377-447-503 UL CB
OM-505	505	2	0	30.04.1992	Operators manual 505 with decompressor
OM-505	505 A	2	0	30.04.1992	Operators manual 505 A with decompressor
OM-505	505	2	0	30.04.1992	Operators manual 505 without decompressor
OM-535	535 B,535 A	2	0	01.01.1992	Operators Manual 535 A (dual carburetor horizontal) Operators Manual 535 B (dual carburetor vertical)
OM-535	535 C	2	0	01.01.1992	Operators manual 535 C (single carburetor)
OM-582,OM-503,OM-447	582 UL,503 UL,447 UL	2	0	01.09.2010	Operators Manual for engine types 447 UL SCDI, 503 UL DCDI, 582 UL DCDI mod. 90 and 582 UL DCDI mod. 99
OM-618	618 UL	1	0	01.06.1994	Operators manual ROTAX 618 UL (preliminary)
OM-912	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	4	0	27.01.2017	Operators Manual 912 Series
OM-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	3	01.08.2015	Operators Manual ROTAX 912 i Series, Rev. 2

Document Type	Engine Type	Issue	Revision	Date	Title
OM-912i	912 iSc SPORT,912 iS SPORT,912 iS	1	3	01.08.2015	Revision pages for Operators Manual ROTAX 912 i Series, Rev.3
OM-914	914 UL,914 F	2	2	01.02.2015	Revision Pages for Operators Manual 914 Series, Revision 2
OM-914	914 UL,914 F	2	2	01.02.2015	Operators Manual 914 Series
RM-277	277 UL	0	2	01.01.1993	Repair manual 277 UL
RM-503,RM-447	503 UL,447 UL	0	1	01.12.1989	Repair manual engine types 377-447-503 UL CB
RM-505	505 A,505	1	3	01.01.1993	Repair Manual 501/505 (Serie)
RM-582	582 UL	0	1	01.04.1995	Repair manual 462-532-582 UL
SB-2ST-001	582 UL	0	0	01.12.2001	Checking or replacement of tension spring on exhaust system for ROTAX engine type 582 UL
SB-2ST-002	582 UL	0	0	01.03.2002	Modified rotary valve cover for ROTAX engine type 582 UL
SB-505-001	505	0	0	26.02.1986	Studs 840 585 (M8x177) connecting cylinders to crankcase (8x)
SB-505-002	505	0	0	20.09.1988	Conversion of engine types 505 into 505 A (type certificate data sheet TW 3/78, issue no. 5
SB-505-003	505 A,505	0	0	20.09.1988	Check of ignition timing after exchange of an electronic box
SB-505-004	505 A,505	0	0	13.04.1989	Examination of the starter gear for cracks.
SB-505-005	505 A,505,501	0	0	01.08.1989	Piston pin bearing, conversion to reinforced design **(for 501 see SB-505-005)
SB-505-006	505 A,505	0	0	29.01.1992	Introduction of a new electronic box with a modified wiring on the stator plate.
SB-505-007	505 A,505,501	0	0	02.12.1997	TBO of ROTAX engine type 501, 505 and 505 A. **(for 501 see SB-505-007)
SB-505-008	505 A,505	0	0	22.01.1999	Magneto housing for ROTAX engine type 505 (series)
SB-505-009	505 A,505	0	1	01.03.2003	New charging coil assy. with support for Rotax engine type 505
SB-535-001	535 B,535 A	0	0	31.01.1984	Flywheel on drive side
SB-535-002	535 B,535 A	0	0	05.12.1985	Coil brace 866 780 connecting charging coil with lighting coil on armature plate assy.
SB-535-003	535 B,535 C,535 A	0	0	20.09.1988	Check of ignition timing after exchange of an electronic box.
SB-535-004	535 C,535 B,535 A	0	0	21.03.1989	Fixation of charging coil and lighting coil on armature plate assy.
SB-535-005	535 C,535 B,535 A	0	0	13.04.1989	Examination of the starter gear for cracks.
SB-535-006	535 C,535 B,535 A	0	0	05.06.1992	Introduction of a new electronic box with a modified wiring on the stator plate.
SB-535-007	535 B,535 A	0	1	01.02.1999	Magneto housing for ROTAX engine type 535 (Series)
SB-535-008	535 C,535 B,535 A	0	1	28.01.2005	New charging coil assy. with support for Rotax engine type 535
SB-535-009,SB-505-010,SB-501,SB-275	535 C,535 B,535 A,505 A,505,501,275	0	1	04.05.2007	New maintenance schedule, checklist and engine preservation for ROTAX engine type 275, 501, 505 and 535
SB-912-000, SB-914-000, SB-912i-000, SB-535-000,SB-505-000	535 C,535 B,535 A,505 A,505,914 F,912 S,912 F,912 A,912 iSc SPORT	0	-	24.02.2017	Publication Index for ROTAX Aircraft Engines
SB-912-000UL,SB-914-000UL,SB-912i-000iS, SB-2ST-000	912 iS,912 ULS,914 UL,447 UL,503 UL,618 UL,912 UL,912 iS SPORT,582 UL,277 UL	0	1	24.02.2017	Publication Index for ROTAX Aircraft Engines

Document Type	Engine Type	Issue	Revision	Date	Title
SB-912-001	912 A	0	0	13.08.1992	Engine type 912 A, Ignition unit with resistor spark plug
SB-912-002	912 A	0	1	29.11.1993	Ignition for ROTAX 912 A
SB-912-003	912 A	0	0	28.09.1993	CANCELLED - Operators manual for ROTAX 912 A - superseded by Operators manual 912 Series, current edition
SB-912-004	912 A	0	2	14.12.2009	Extension of time between overhauls (TBO) for ROTAX engine type 912 A (Series)
SB-912-004-UL	912 UL	0	2	14.12.2009	Extension of time between overhauls (TBO) for ROTAX engine type 912 UL (Series)
SB-912-005	912 A	0	3	14.12.2009	Special inspection to increase the TBO for ROTAX engine type 912 A (Series)
SB-912-005	912 A	0	2	29.07.1996	Special inspection to increase the TBO for engine 912 A Serie
SB-912-005-UL	912 UL	0	0	14.12.2009	Special inspection to increase the TBO for ROTAX engine type 912 UL (Series)
SB-912-006	912 A	0	0	28.11.1994	Grounding cable for electronic module of ROTAX Engine series Type 912 A
SB-912-007	912 A	0	0	01.02.1995	Ground connection for pick up wiring, ROTAX Engine Series Type 912 A
SB-912-007-UL	912 UL	0	0	20.12.2007	Ground connection for pick-up wiring for ROTAX engine type 912 (Series)
SB-912-008	912 A	0	0	24.08.1995	Electronic module with pi-filter, ROTAX Engine Series 912 A
SB-912-009	912 A	0	0	12.09.1995	Contamination of carburetors, ROTAX 912 A (series)
SB-912-010	912 F,912 A	0	0	08.02.1996	Fitting of a carburetor support, ROTAX 912 A/F (series)
SB-912-010-UL	912 UL	0	0	20.12.2007	Fitting of a carburetor support for ROTAX engine type 912 (Series)
SB-912-011	912 F,912 A	0	1	01.11.1999	CANCELLED - Use of an adapted propeller governor on Rotax engine type 912 A3 and 912 F3, superseded by SB-912-052/SB-914-035, latest edition
SB-912-012	912 A	0	0	13.08.1996	Modification on ROTAX 912 A4
SB-912-013	912 ULS,912 UL,912 S,912 F,912 A	0	0	29.07.1996	CANCELLED - Motor oil for ROTAX 912 Series - superseded by SI-18-1997 latest edition
SB-912-014	912 F,912 A	0	2	14.12.2009	Extension of time between overhauls (TBO) for ROTAX engine type 912 A and 912 F (Series)
SB-912-015	912 F,912 A	0	0	29.07.1996	Replacement of rocker arms on ROTAX 912 A/F (series)
SB-912-015-UL	912 UL	0	0	20.12.2007	Replacement of rocker arms for ROTAX engine type 912 (Series)
SB-912-016	912 A	0	0	13.08.1996	External alternator for engine type 912, model A2, A3 and A4
SB-912-017,SB-914-037	912 F,912 A,914 F	0	-	20.12.2007	Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series)
SB-912-017-UL,SB-914-037-UL	912 UL,914 UL	0	-	20.12.2007	Checking or replacement of oil filter for ROTAX engine type 912 and 914 (Series)
SB-912-018	912 A	0	1	18.03.1997	Cam shaft check engine type ROTAX 912 A (series)
SB-912-019	912 A	0	0	09.07.1997	Propeller gear box for ROTAX 912 A3
SB-912-020	912 F,912 A	0	1	10.02.1998	Fuel pump for Engine type ROTAX 912 F and 912 A (series)
SB-912-020-UL	912 UL	0	0	20.12.2007	Replacement of the fuel pump part no. 996592 for ROTAX engine type 912 (Series)
SB-912-021	912 F	0	0	17.12.1997	CANCELLED - Operator's manual for ROTAX 912 F - superseded by Operator's manual 912 Series, latest edition
SB-912-022,SB-914-011	912 S,912 F,912 A,914 F	0	0	01.03.2001	Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (series)

Document Type	Engine Type	Issue	Revision	Date	Title
SB-912-022-UL,SB-914-011-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	13.03.2001	Replacement of valve spring retainer on single valve spring configuration of ROTAX engine type 912 und 914 (Series)
SB-912-023	912 F,912 A	0	0	25.05.1998	Inspection of the fuel pump kit, part no. 996.594
SB-912-024	912 F,912 A	0	0	22.10.1998	CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T1, superseded by SB-912-052/SB-914-035, latest edition
SB-912-025	912 F,912 A	0	0	22.10.1998	CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T2, superseded by SB-912-052/SB-914-035, latest edition
SB-912-026,SB-914-014	912 F,912 A,914 F	0	3	01.12.1999	Checking and replacement of stator assy.
SB-912-026-UL,SB-914-014-UL	912 ULS,912 UL,914 UL	0	3	01.12.1999	Checking and replacement of stator assy.
SB-912-027,SB-914-010	912 F,912 A,914 F	0	1	01.02.2000	Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914
SB-912-027-UL,SB-914-010-UL	912 UL,914 UL	0	1	01.02.2000	Checking or replacement of the propeller gearbox for all versions of the Rotax engine type 912 and 914
SB-912-028,SB-914-016	912 S,912 F,912 A,914 F	0	1	01.11.2002	Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (Series)
SB-912-028-UL,SB-914-016-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	01.11.2002	Checking or replacement of engine suspension frame part no. 886 567 on ROTAX engine type 912 and 914 (series)
SB-912-029,SB-914-018	912 S,912 F,912 A,914 F	0	3	11.07.2006	Checking of crankcase on ROTAX engine type 912 and 914 (Series)
SB-912-029-UL,SB-914-018-UL	912 ULS,912 ULSFR,912 UL,914 UL	0	3	11.07.2006	Checking of the crankcase on ROTAX engine type 912 and 914 (Series)
SB-912-030,SB-914-019	912 S,912 F,912 A,914 F	0	1	01.02.2004	Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series)
SB-912-030-UL,SB-914-019-UL	912 ULS,912 ULSFR,912 UL,914 UL	0	1	01.02.2004	Cracks, wear and distortion on the carburetor flange on Rotax engine type 912 and 914 (series)
SB-912-031	912 S,912 F,912 A	0	0	01.10.2001	Checking or replacement of the fuel pump assembly part no. 996 596 on ROTAX engine tpye 912 (series)
SB-912-031-UL	912 ULSFR,912 ULS,912 UL	0	0	01.10.2001	Checking or replacement of the fuel pump assembly part no. 996 596 on ROTAX engine tpye 912 (series)
SB-912-032	912 A	0	0	01.10.2001	Replacement of oil pump assy. or oil pump shaft assy. on ROTAX engine type 912 A (series)
SB-912-032-UL	912 UL	0	0	01.10.2001	Replacement of oil pump assy. or oil pump shaft assy. on ROTAX engine type 912 UL
SB-912-033,SB-914-020	912 S,912 F,912 A,914 F	0	0	01.08.2002	Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914
SB-912-033-UL,SB-914-020-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	0	01.08.2002	Inspection of the propeller gearbox when using leaded fuel for ROTAX engine 912/914
SB-912-034	912 A	0	0	01.03.2002	Checking of oil pump attachment screw for ROTAX engine type 912 A (Series)
SB-912-034-UL	912 UL	0	0	01.03.2002	Checking of oil pump attachment screw for ROTAX engine type 912 UL (Series)

Document Type	Engine Type	Issue	Revision	Date	Title
SB-912-035,SB-914-021	912 S,912 F,912 A,914 F	0	1	01.09.2002	Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series)
SB-912-035-UL,SB-914-021-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	01.09.2002	Inspection or replacement of the rocker arms and valve push-rods for Rotax engine type 912 and 914 (Series)
SB-912-036,SB-914-022	912 S,912 F,912 A,914 F	0	1	23.01.2007	CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040/SB-914-026, latest edition
SB-912-036-UL,SB-914-022-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	23.01.2007	CANCELLED - Inspection for correct venting of the oil system for Rotax engine type 912 and 914 (Series), superseded by SB-912-040UL/SB-914-026UL, latest edition
SB-912-037,SB-914-023	912 S,912 F,912 A,914 F	0	1	01.10.2003	Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie)
SB-912-037-UL,SB-914-023-UL	912 ULS,912 UL,912 ULSFR,914 UL	0	0	01.10.2002	Installation of an electric starter with enhanced power for Rotax Motor Type 912 und 914 (Serie)
SB-912-038,SB-914-024	912 S,912 F,912 A,914 F	0	0	01.11.2002	CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series)
SB-912-042	912 S	0	1	01.04.2004	Checking of the engine in case of excessive propeller backlash for Rotax engine type 912 S
SB-912-042-UL	912 ULSFR,912 ULS	0	1	01.04.2004	Checking of the engine in case of excessive propeller backlash for Rotax engine type 912 S
SB-912-044	912 F,912 A	0	1	28.05.2010	Use of the Rotax supplied airbox for all Rotax engine types 912 A/F (Series)
SB-912-044-UL	912 UL	0	1	28.05.2010	Use of the Rotax supplied airbox for all Rotax engine types 912 UL (Series)
SB-912-049	912 S,912 F,912 A	0	0	24.05.2006	Checking eccenters and fuel pump plungers for Rotax engine type 912 (series)
SB-912-049-UL	912 ULS,912 ULSFR,912 UL	0	0	24.05.2006	Checking eccenters and fuel pump plungers for Rotax engine type 912 (series)
SB-912-050	912 S,912 F,912 A	0	0	24.05.2006	CANCELLED - Checking or replacement of fuel pump part no. 892230/892235 on Rotax engine type 912 (series), superseded by ASB-912-053 latest edition
SB-912-050-UL	912 ULS,912 ULSFR,912 UL	0	0	24.05.2006	CANCELLED - Checking or replacement of fuel pump part no. 892230/892235 on Rotax engine type 912 (series), superseded by ASB-912-053 latest edition
SB-912-053	912 S,912 F,912 A	0	0	13.04.2007	Replacement of fuel pump for Rotax engine type 912 (Series)
SB-912-053-UL	912 ULSFR,912 ULS,912 UL	0	0	13.04.2007	Replacement of fuel pump for Rotax engine type 912 (Series)
SB-912-054	912 S,912 F,912 A	0	0	29.05.2007	Checking or replacement of flexible fuel line for Rotax engine type 912 (Series)
SB-912-054-UL	912 ULSFR,912 ULS,912 UL	0	0	29.05.2007	Checking or replacement of flexible fuel line for Rotax engine type 912 (Series)
SB-912-057	912 S,912 F,912 A	0	1	24.05.2016	Extension of Time Between Overhauls (TBO) for ROTAX Engine Type 912 (Series)
SB-912-057-UL	912 ULSFR,912 ULS,912 UL	0	0	14.12.2009	Extension of time between overhauls (TBO) for ROTAX engine type 912 (Series)
SB-912-063	912 S,912 F,912 A	0	1	24.06.2013	Replacement of Fuel Pumps for Rotax Engine Type 912 (Series)
SB-912-063-UL	912 ULS,912 UL,912 ULSFR	0	2	21.08.2013	Replacement of Fuel Pumps for Rotax Engine Type 912 (Series)
SB-912-064,SB-914-045	912 S,912 F,912 A,914 F	0	1	11.11.2013	Periodic checking of the crankshaft journal (power take off side) for ROTAX Engine Type 912 and 914 (Series)

Document Type	Engine Type	Issue	Revision	Date	Title
SB-912-064-UL,SB-914-045-UL	912 ULS,912 ULSFR,912 UL,914 UL	0	1	11.11.2013	Periodic checking of the crankshaft journal (power take off side) for ROTAX Engine Type 912 and 914 (Serie)
SB-912-065 UL,SB-914-046 UL	912 UL,914 UL,912 ULS	0	3	26.03.2015	Periodic inspection of the float buoyancy for ROTAX Engine Type 912 and 914 (Series)
SB-912-065,SB-914-046	912 S,912 F,912 A,914 F	0	3	26.03.2015	Periodic inspection of the float buoyancy for ROTAX Engine Type 912 and 914 (Series)
SB-912-066,SB-914-047	912 S,912 F,912 A,914 F	0	1	23.04.2015	Change of Measurement Method from Cylinder Head Temperature to Coolant Temperature for ROTAX® Engine Type 912 and 914 (Series)
SB-912-066-UL,SB-914-047-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	23.04.2015	Change of Measurement Method from Cylinder Head Temperature to Coolant Temperature for ROTAX® Engine Type 912 and 914 (Series)
SB-912-067,SB-914-048	912 S,912 F,912 A,914 F	0	1	26.03.2015	Exchange of floats on ROTAX Engine Type 912 and 914 (Series)
SB-912-067-UL,SB-914-048-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	1	26.03.2015	Exchange of floats on ROTAX Engine Type 912 and 914 (Series)
SB-912-068,SB-914-049	912 S,912 F,912 A,914 F	0	1	09.09.2015	Specification/Change of Engine Configuration and/or Type Plate for ROTAX Engine Type 912 and 914 (Series)
SB-912-068-UL,SB-914-049-UL	912 ULSFR,912 ULS,912 UL,914 UL	0	2	09.09.2015	Specification/Change of Engine Configuration and/or Type Plate for ROTAX Engine Type 912 and 914 (Series)
SB-912i-001,SB-914-035,SB-912-052	912 iSc SPORT,914 F,912 S,912 F,912 A	0	-	13.06.2014	Installation / Use of governors for Rotax engine type 912i, 912 and 914
SB-912i-001iS,SB-914-035-UL,SB-912-052-UL	912 iS,914 UL,912 ULSFR,912 ULS,912 UL,912 iS SPORT	0	-	13.06.2014	Installation / Use of governors for Rotax engine type 912i, 912 and 914 (Series)
SB-912i-002iS	912 iS	0	0	18.12.2013	Flashing of a new Software on the Engine Control Unit 912 iS (ECU) for ROTAX Engine Type 912 i (Series)
SB-912i-003iS	912 iS	0	1	03.06.2014	Installation instructions for upgrade kit 912 iS Sport for ROTAX engine type 912 i (Series)
SB-912i-004iS	912 iS	0	0	03.09.2014	Replacement of Regulator A and Regulator B for ROTAX Engine Type 912 i (Series)
SB-912i-006	912 iSc SPORT	0	0	26.05.2016	Exchange of stator assy. of ROTAX Engine Type 912 i (Series)
SB-912i-006iS	912 iS SPORT,912 iS	0	0	26.05.2016	Exchange of stator assy. of ROTAX Engine Type 912 i (Series)
SB-914-001	914 F	0	0	06.02.1997	CANCELLED - Use of an adapted propeller governor on engine type ROTAX 914 F3, superseded by SB-912-052/SB-914-035, latest edition
SB-914-002	914 F	0	0	24.02.1997	Modification of engine type ROTAX 914 F3
SB-914-003	914 F	0	0	09.07.1997	Calibration of the mixture enrichment jet of engine type ROTAX 914 F (series)
SB-914-003-UL	914 UL	0	0	20.12.2007	Calibration of the mixture enrichment jet for ROTAX engine type 914 (Series)
SB-914-004	914 F	0	0	27.08.1997	Checking of the banjo bolt in the pressure oil line of turbo charger for ROTAX 914 (series)
SB-914-004-UL	914 UL	0	0	20.12.2007	Checking of the banjo bolt in the pressure oil line of turbocharger for ROTAX engine type 914 (Series)
SB-914-005	914 F	0	0	29.07.1998	Introduction of a turbo charger with a modified wastegate on Rotax 914

Document Type	Engine Type	Issue	Revision	Date	Title
SB-914-005-UL	914 UL	0	0	20.12.2007	Introduction of a turbocharger with modified waste-gate for ROTAX engine type 914 (Series)
SB-914-006	914 F	0	1	01.10.2002	Employment of a muffler of reduced noise emission on ROTAX engine Type 914 F (series).
SB-914-006-UL	914 UL	0	0	01.10.2002	Employment of a muffler of reduced noise emission on ROTAX engine Type 914 F (series).
SB-914-007	914 F	0	0	05.06.1998	ROTAX engine type 914 F (series), check / replacement of the turbo oil pressure line and pipe clamps
SB-914-007-UL	914 UL	0	0	20.12.2007	Check/replacement of the turbo oil pressure line and pipe clamps for ROTAX engine type 914 (Series)
SB-914-008	914 F	0	0	05.06.1998	ROTAX engine type 914 F (series) check / replacement of the wastegate servo cable
SB-914-008-UL	914 UL	0	0	20.12.2007	Check/replacement of the waste-gate servo cable for ROTAX engine type 914 (Series)
SB-914-009	914 F	0	0	22.10.1998	CANCELLED - Installation of propeller governor McCauley DCFU290D17B/T2, superseded by SB-912-052/SB-914-035, latest edition
SB-914-012	914 F	0	0	29.09.1998	ROTAX engine series type 914 F, verification of the wiring harness
SB-914-012-UL	914 UL	0	0	20.12.2007	Verification of the wiring harness for ROTAX engine type 914 (Series)
SB-914-013	914 F	0	0	31.03.1999	Turbocharge control unit (TCU) with software level according to RTCA DO 178 B, for engine Type 914 F (series)
SB-914-013-UL	914 UL	0	0	20.12.2007	Turbocharge control unit (TCU) with software level D according to RTCA DO 178 B for ROTAX engine type 914 (Series)
SB-914-015	914 F	0	0	01.01.2001	Checking or replacement of the exhaust muffler of reduced noise emission part no. 979405 for ROTAX engine type 914 F
SB-914-017	914 F	0	1	01.07.2002	Checking or replacement of exhaust bend on ROTAX engine type 914 (Series)
SB-914-017-UL	914 UL	0	1	01.07.2002	Checking or replacement of the exhaust bend on ROTAX engine type 914 (series)
SB-914-024-UL, SB-912-038-UL	914 UL, 912 ULSFR, 912 ULS, 912 UL	0	0	01.11.2002	CANCELLED - Revision of Operators Manual for ROTAX engine type 912 and 914 (Series)
SB-914-025, SB-912-039	914 F, 912 S, 912 F, 912 A	0	0	01.12.2002	Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series)
SB-914-025-UL, SB-912-039-UL	914 UL, 912 ULSFR, 912 ULS, 912 UL	0	0	01.12.2002	Modifications of the overflow bottle for ROTAX engine type 912 and 914 (Series)
SB-914-026, SB-912-040	914 F, 912 S, 912 F, 912 A	0	1	01.08.2003	Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series)
SB-914-026-UL, SB-912-040-UL	914 UL, 912 ULSFR, 912 ULS, 912 UL	0	0	01.04.2003	Introduction of a new oil dipstick for ROTAX engine type 912 and 914 (Series)
SB-914-027, SB-912-041	914 F, 912 S, 912 F, 912 A	0	2	25.03.2010	Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series)
SB-914-027-UL, SB-912-041-UL	914 UL, 912 ULSFR, 912 ULS, 912 UL	0	2	25.03.2010	Extension of Time Between Overhaul (TBO) for ROTAX engine type 912 and 914 (Series)
SB-914-028	914 F	0	1	08.11.2004	Inspection of exhaust muffler part no. 979402 / 979404 for Rotax engine type 914 (Series)
SB-914-028-UL	914 UL	0	1	08.11.2004	Inspection of exhaust muffler part no. 979402 / 979404 for Rotax engine type 914 (Series)

Document Type	Engine Type	Issue	Revision	Date	Title
SB-914-029,SB-912-043	914 F,912 S,912 F,912 A	0	2	10.11.2006	Change of coolant specification on ROTAX engine type 912 and 914 (Series)
SB-914-029-UL,SB-912-043-UL	914 UL,912 ULSFR,912 ULS,912 UL	0	1	28.08.2006	Change of coolant specification on ROTAX engine type 912 and 914 (Series)
SB-914-030,SB-912-045	914 F,912 S,912 F,912 A	0	0	19.11.2004	Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series)
SB-914-030-UL,SB-912-045-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	19.11.2004	Inspection of the oil filter part no. 825701 for Rotax engine type 912 and 914 (Series)
SB-914-031,SB-912-046	914 F,912 S	0	0	26.07.2005	Check of the support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series)
SB-914-031-UL,SB-912-046-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	26.07.2005	Check of support bearing on the crankshaft and of the bearing bushing in the propeller gearbox on Rotax engine type 912/914 (Series)
SB-914-032,SB-912-047	914 F,912 S	0	0	29.07.2005	Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series)
SB-914-032-UL,SB-912-047-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	29.07.2005	Check of Allen screw M8x100 in the crankcase on Rotax engine type 912/914 (Series)
SB-914-033,SB-912-048	914 F,912 S,912 F,912 A	0	0	23.09.2005	Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series)
SB-914-033-UL,SB-912-048-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	23.09.2005	Replacement of pin part no. 929700 in carburetor for Rotax engine type 912 and 914 (series)
SB-914-034,SB-912-051	914 F,912 S,912 F,912 A	0	0	30.01.2008	Checking of magnetic plug on Rotax engine type 912/914 (Series)
SB-914-034-UL,SB-912-051-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	30.01.2008	Checking of magnetic plug on Rotax engine type 912/914 (Series)
SB-914-036,SB-912-055	914 F,912 S,912 F,912 A	0	0	31.08.2007	Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series)
SB-914-036-UL,SB-912-055-UL	914 UL,912 ULSFR,912 ULS,912 UL	0	0	31.08.2007	Inspect for tight fit of oil filter for Rotax engine type 912 and 914 (Series)
SB-914-038,SB-912-056	914 F,912 S	0	1	05.08.2008	Replacement of the propeller gearbox for some Rotax engines type 912/914 (Series)
SB-914-038-UL,SB-912-056-UL	914 UL,912 ULSFR,912 ULS	0	1	05.08.2008	Replacement of the propeller gearbox for some ROTAX engines type 912/914 (Series)
SB-914-039	914 F	0	0	25.03.2010	Extension of time between overhauls (TBO) for ROTAX engine type 914 (Series)
SB-914-039-UL	914 UL	0	0	25.03.2010	Extension of time between overhauls (TBO) for ROTAX engine type 914 (Series)
SB-914-040	914 F	0	0	10.03.2011	Replacement of fuel pressure regulator part no. 887130 for ROTAX engine type 914 (Series)
SB-914-040-UL	914 UL	0	0	10.03.2011	Replacement of fuel pressure regulator assy. part no. 887130 for ROTAX engine type 914 (Series)
SB-914-041,SB-912-058	914 F,912 S,912 F,912 A	0	0	15.04.2011	Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series)

Document Type	Engine Type	Issue	Revision	Date	Title
SB-914-041-UL,SB-912-058-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	15.04.2011	Replacement of washer part no. 944072 (flywheel hub) for ROTAX engine type 912 and 914 (Series)
SB-914-042,SB-912-059	914 F,912 S,912 F,912 A	0	0	01.01.2012	Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series)
SB-914-042-UL,SB-912-059-UL	914 UL,912 ULS,912 ULSFR,912 UL	0	0	01.01.2012	Checking of the crankshaft journal (power take off side) for ROTAX engine type 912 and 914 (Series)
SB-914-050	914 F	0	0	13.05.2015	Replacement of the overload clutch of ROTAX® Engine Type 914 (Series)
SB-914-050-UL	914 UL	0	0	13.05.2015	Replacement of the overload clutch of ROTAX® Engine Type 914 (Series)
SI-01-1985	532 UL,503 UL,462 UL,447 UL,377 UL	0	0	01.04.1985	UL-Propeller-Gear
SI-01-1988	532 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.01.1988	Function test of rectifier regulator
SI-01-1989	503 UL	0	0	01.03.1989	Fan drive of engine Type 503
SI-01-1991	582 UL,532 UL	0	0	01.02.1991	Rotary valve shaft sealing for ROTAX 532 UL and 582 UL
SI-01-1992	912 UL	0	0	01.07.1992	Engine type 912 UL, ignition unit with resistor spark plug
SI-01-1993	582 UL	0	0	01.01.1993	ROTAX 582 UL DCDI - making of pick-up
SI-01-1994	912 A,912 UL	0	0	01.01.1994	Electronic-box for ROTAX 912 A + UL
SI-01-1995	912 UL	0	1	01.04.1995	CANCELLED - Ground connection for pick-up wiring, ROTAX engine Series Type 912 UL, superseded by SB-912-007 UL, latest edition
SI-01-1998	912 UL	0	1	01.02.1998	CANCELLED - Fuel pump 996592 (pump with screw fittings) 912 (series), superseded by SB-912-020 UL, latest edition
SI-02-1984	277 UL	0	0	25.01.1984	UL-Propeller-Gear 277
SI-02-1985	532 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.05.1985	Increase of ignition voltage on BOSCH contact ignition
SI-02-1991	618 UL,582 UL,503 UL	0	0	01.02.1991	Tightening torque increase on 'C' gearboxes for UL-engines.
SI-02-1992	912 A,912 UL	0	0	01.12.1992	Coolant expansion tank ROTAX 912
SI-02-1995	912 A,912 ULSFR,912 ULS,912 UL,912 S,912 F	2	0	01.08.1995	Contamination of carburetors, ROTAX-series 912
SI-02-1996	912 UL,912 A	0	0	01.02.1996	Rectifier regulator, Rotax Series 912
SI-02-1997	912 UL	0	0	01.02.1997	Camshaft check on ROTAX engine Type 912 UL (series)
SI-02-1998	914 F,914 UL	0	0	01.06.1998	CANCELLED - ROTAX engine type 914, check / replacement of the turbo oil pressure line and pipe clamps, superseded by SB-914-007 UL, latest edition
SI-03-1985	277 UL	0	0	01.09.1985	UL-Propeller-Gear 277
SI-03-1985	277 UL	0	0	01.09.1985	UL-Propeller Gear 277
SI-03-1989	532 UL,503 UL,447 UL,377 UL	0	0	01.06.1989	Matching a propeller to ROTAX UL-Engines.
SI-03-1991	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.04.1991	Daily and Pre-Flight-Check - Maintenance plan for all ROTAX engines
SI-03-1993	912 UL	0	0	01.02.1993	Ignition unit of ROTAX 912 UL
SI-03-1994	912 UL,912 A	0	0	01.12.1994	Sensor and gauge for oil pressure indication-ROTAX 912
SI-03-1996	618 UL,582 UL,532 UL,462 UL	0	1	01.09.1999	Rotary valve shaft seal leakage at Rotax engine type 462 UL / 532 UL / 582 UL and 618 UL

Document Type	Engine Type	Issue	Revision	Date	Title
SI-03-1997	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	1	01.01.1999	CANCELLED - Coolant (antifreeze) mixtures for ROTAX engine type 912/914 (Series) - superseded by relevant Operators Manual, latest edition
SI-03-1998	914 UL,914 F,912 UL,912 S,912 F,912 A	0	1	01.02.2004	Engine start at low temperatures at Rotax engine type 912 and 914 (Series)
SI-03-1999	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	0	01.02.1999	Standardization of the crankcase for ROTAX engines 912 and 914
SI-04-1986	532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.09.1986	Possible causes for piston seizures or holes in pistons
SI-04-1987	582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	1	0	01.05.1990	Ultralight engines-unexpected engine stops
SI-04-1989	582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.01.1989	Use of tool for cageless piston pin needle bearing
SI-04-1990	582 UL	0	0	01.09.1990	Starter gear - electric starter, magneto side, on engine 582 UL
SI-04-1993	582 UL	0	0	01.09.1993	Crankcase modifications - ROTAX 582 DCDI
SI-04-1994	532 UL,914 UL,912 UL,618 UL,582 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.02.1994	Carburetor icing on UL-engines
SI-04-1995	912 F,912 A,912 UL	0	0	01.05.1995	Floats with a new shape, engine Series Type 912
SI-04-1997	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	3	23.01.2007	CANCELLED - Venting of lubrication system for Rotax engine type 912 and 914 (Series), superseded by SI-912-018/SI-914-020, latest edition
SI-04-1998	914 F,914 UL	0	1	01.06.1998	CANCELLED - ROTAX engine type 914 F (series) Replacement of the waste gate servo cable, superseded by SB-914-008 UL, latest edition
SI-05-1988	447 UL,532 UL,503 UL,462 UL,377 UL	0	0	01.04.1990	Gearbox fixation on UL-engines type 377 to 532 UL
SI-05-1990	582 UL,503 UL	0	1	01.12.1990	Disturbance of tachometer 966 072 for 503 UL C.D.I. and 582 UL with DUCATI ignition unit
SI-05-1991	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.12.1991	Piston for ROTAX UL engines (2-stroke)
SI-05-1994	912 UL,912 A	0	0	01.03.1994	Banjo Bolt ROTAX 912
SI-05-1995	912 UL	0	2	01.07.1996	External alternator for engine series type 912 UL, Mod. 94
SI-05-1996	503 UL,447 UL	0	0	01.03.1997	Cracks in the carburetor socket, ROTAX 447 and 503 UL
SI-05-1997	914 UL,914 F,912 UL,912 F,912 A	0	1	01.04.1997	Exhaust flange of ROTAX engines 912/914 (series)
SI-05-1998	914 UL,914 F	0	0	01.06.1998	Acceptable cracks in the turbine housing of the turbo charger for engine 914
SI-05-1999	914 UL	0	0	01.10.1999	CANCELLED - Turbocharge control unit (TCU) with software level according to RTCA DO 178 B, for ROTAX engine Type 914 F (series), superseded by SB-914-013 UL, latest edition
SI-06-1986	377 UL,277 UL,532 UL,508 UL,503 UL,462 UL,447 UL	0	0	01.12.1986	UL-Reduction gear box
SI-06-1987	582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.07.1987	Engine-Instruments
SI-06-1993	582 UL	0	0	01.09.1993	ROTAX 582 UL carb adapter

Document Type	Engine Type	Issue	Revision	Date	Title
SI-06-1994	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.07.1994	Incorrect Model fuel pumps without bleed hole, ROTAX 2-cycle engines
SI-06-1995	912 UL	0	2	01.07.1996	External alternator for engine series type 912 UL, Mod. 89 and 91
SI-06-1996	618 UL,582 UL,503 UL	0	0	01.03.1997	Modifications on reduction gearbox 'C' and 'E'
SI-06-1997	914 UL,914 F,912 UL,912 F,912 A	0	1	18.02.2005	Friction torque check of propeller gear with overload clutch on Rotax engine type 912 and 914 (Series)
SI-06-1998	618 UL,582 UL,532 UL,503 UL,447 UL	0	1	01.07.2001	Amendment on reduction gearbox type 'C' and type 'E' for 2-stroke UL aircraft engines
SI-06-1999	912 ULS,912 S	0	0	01.01.1998	ROTAX engine Type 912 ULS/S, Oil consumption
SI-07-1987	582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	1	0	01.04.1990	Fuel consumption, 2-stroke UL-Engine
SI-07-1991	508 UL,447 UL	0	0	01.05.1991	Wiring diagr. for 447 UL SCDI and 508 UL SCDI in conj. with electr. tachometer
SI-07-1993	447 UL	0	0	01.09.1993	Revolution counter for ROTAX 447 SCDI
SI-07-1994	582 UL	0	0	01.07.1994	ROTAX 582 UL crankshaft
SI-07-1995	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,532 UL,503 UL,447 UL,377 UL,277 UL	0	1	01.02.1999	New airfilter with securing tab
SI-07-1996	912 UL	0	0	01.09.1996	CANCELLED - Replacement of rocker arms on ROTAX 912 UL (series), superseded by SB-912-015 UL, latest edition
SI-07-1997	914 UL	0	0	01.07.1997	CANCELLED - Calibration of the mixture enrichment jet of ROTAX 914 UL (series), superseded by SB-914-003 UL, latest edition
SI-07-1998	503 UL	0	0	12.10.1998	'B' type gearbox installation, ROTAX 503 UL DCDI (all versions)
SI-08-1987	582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.06.1990	Influence of ambient air temperature and barometric pressure on engine performance and carb calibration
SI-08-1991	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.06.1991	Safety-check of the BING-carburetors used in all ROTAX UL-engines
SI-08-1993	912 UL,912 A	0	0	01.10.1993	CANCELLED - General overhaul of ROTAX 912 A/UL, superseded by SB for TBO Extension, latest edition
SI-08-1994	582 UL	0	0	01.05.1994	Attaching of water pump housing on ROTAX 582 UL
SI-08-1995	912 UL	0	1	01.12.1995	CANCELLED - Fitting of a carburetor support, Rotax Series 912, superseded by SB-912-010 UL, latest edition
SI-08-1996	618 UL	0	0	01.03.1997	Installation of oversize pistons, ROTAX 618 UL
SI-08-1998	914 UL	0	1	01.02.1999	CANCELLED - ROTAX engine series type 914 UL, verification of the wiring harness, superseded by SB-914-012 UL, latest edition
SI-08-1999	582 UL,503 UL,447 UL	0	0	01.02.1999	CANCELLED - Documentations for 447 - 503 - 582 - 582 Mod. 99, superseded by SL-2ST-002, latest edition
SI-09-1991	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.11.1991	Installation Instructions for ROTAX UL-engines
SI-09-1993	618 UL	0	0	01.11.1993	Assembly instructions for ROTAX 618 water pump cover
SI-09-1994	618 UL,582 UL,532 UL,503 UL	0	2	01.01.2004	Installation Instruction of UL reduction gearbox type 'C' and 'CL'

Document Type	Engine Type	Issue	Revision	Date	Title
SI-09-1996	914 UL	0	0	01.03.1998	ROTAX 914 UL exchange of the oilpump housing
SI-09-1997	503 UL	0	0	01.07.1997	Exchange of piston pins, ROTAX 503 UL
SI-10-1987	503 UL	0	0	01.11.1987	503 UL- FREE AIR Version
SI-10-1991	912 A,912 UL	0	0	01.09.1991	Water distributor for ROTAX 912 A and 912 UL
SI-10-1994	618 UL,582 UL,532 UL,503 UL	0	2	01.01.2004	Installation Instruction of UL reduction gearbox type 'E' and 'EL'
SI-10-1996	618 UL,582 UL,532 UL,503 UL,447 UL,377 UL,277 UL	0	0	01.05.1997	Piston pin circlip installation (2-stroke UL-engines)
SI-10-1999	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	0	01.03.1999	Illustrated Parts Catalog (IPC) for ROTAX engines 912 / 914 (series)
SI-11-1987	532 UL,503 UL,447 UL,377 UL	0	0	01.11.1987	Exhaust systems for 377/447/462/503/532
SI-11-1991	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.12.1992	Propeller mass moment of inertia
SI-11-1994	503 UL	1	0	01.06.1994	Subsequent install. or retrofit of an oil-Pump for separate oil Lubrication
SI-11-1996	618 UL,582 UL,532 UL,503 UL,447 UL,377 UL,277 UL	0	0	01.01.1998	Engine preservation for 2-stroke- UL- engines
SI-11-1997	914 UL,914 F	0	0	01.12.1997	Adjustment or verification of the wastegate position on ROTAX 914
SI-12-1991	508 UL	0	0	01.12.1992	508 UL-Valve Cover Attachment
SI-12-1994	462 UL,447 UL,377 UL,277 UL,582 UL,532 UL,508 UL,503 UL	0	2	01.01.2004	Installation Instruction of UL reduction gearbox Type 'B'
SI-12-1996	914 F,914 UL,912 F,912 A,912 UL	0	0	01.12.1996	CANCELLED - Oil filter ROTAX 912 / 914 engine, superseded by SB-912-017/SB-914-037 UL, latest edition
SI-12-1997	914 F,914 UL	0	0	01.07.1997	CANCELLED - Checking of the banjo bolt in the pressure oil line of turbo charger for ROTAX engine Type 914 (series), superseded by SB-914-004 UL, latest edition
SI-13-1994	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.07.1994	Using auto fuel in ROTAX two cycle aircraft engine
SI-13-1996	914 UL,914 F,912 UL,912 F,912 A	0	2	23.06.2009	Installation instructions of rev-counter part no. 966403 and 966408 for Rotax engine type 912 and 914 (Series)
SI-13-1997	914 F,914 UL	0	0	01.12.1997	CANCELLED - Introduction of a turbo charger with a modified wastegate on Rotax 914, superseded by SB-914-005 UL, latest edition
SI-14-1994	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.07.1994	ROTAX two-cycle aircraft engines crankshaft failures, piston seizures
SI-14-1997	912 UL,914 F,914 UL,912 F,912 A	0	1	01.03.1998	Introduction of the single valve spring arrangement on Rotax engine type 912 and 914 (series)
SI-15-1994	618 UL,582 UL,532 UL,508 UL,503 UL,447 UL	0	0	01.11.1995	Rev. counter for DUCATI ignition unit

Document Type	Engine Type	Issue	Revision	Date	Title
SI-15-1997	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	0	2	24.11.2010	CANCELLED - Spark plugs for ROTAX engines 912/914 (Series), superseded by Maintenance Manual Line, latest edition
SI-16-1997	914 F,914 UL,912 F,912 A,912 UL	0	1	01.12.1997	Introduction of a modified oil pressure sensor 912/914
SI-17-1994	618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.06.1994	Weight, centre of gravity and moments of inertia of ROTAX UL-engines
SI-17-1997	532 UL,618 UL,582 UL,503 UL,447 UL,377 UL,277 UL	0	0	01.11.1997	Introduction of resistance spark plugs for Rotax 2-stroke engines
SI-18-1994	912 UL	1	0	01.11.1994	Grounding cable for electronic module for ROTAX 912
SI-18-1997	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	5	28.08.2006	CANCELLED - Selection of Motor Oil and General Operating Tips for Rotax engines Type 912 and 914 (series), superseded by SI-912-016/SI-914-019 latest edition
SI-19-1994	582 UL	0	0	01.06.1994	Cylinder and Piston for ROTAX 582 DCDI
SI-19-1997	618 UL	0	0	01.12.1997	Version without intake silencer 618 UL
SI-20-1994	912 UL,912 A	0	3	01.10.1996	Lubrication system for all ROTAX 912
SI-20-1997	377 UL,277 UL,914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,532 UL,503 UL,447 UL	0	0	01.11.1997	New flydat configuration for Rotax UL and aircraft engines
SI-21-1994	912 ULS,912 UL,912 S,912 F,912 A	0	0	01.07.1994	CANCELLED - 912 carburetor fixation, superseded by SB-912-030/SB-914-019 (+UL), latest edition
SI-21-1997	914 F,914 UL,912 F,912 A,912 UL	0	1	01.11.1998	Introduction of the mono hook circlip at ROTAX 912 and 914 series
SI-2-1993	912 UL	0	0	01.01.1993	CANCELLED - Overload clutch for Rotax engine 912 UL, superseded by relevant Maintenance Manual, latest edition
SI-22-1994	582 UL,532 UL,618 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL	0	0	01.12.1994	supply scope of ROTAX crankshafts
SI-22-1997	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	0	01.11.1997	Pressure oil line for hydraulic governor 912/914
SI-25-1994	912 UL	0	0	01.11.1994	Ensuring of a ground connection between screening box part no. 996 611 and engine
SI-25-1997	914 UL,912 UL,912 S,912 F,912 A,912 ULS,914 F	0	11	18.07.2007	CANCELLED - Running modifications on Rotax engine type 912 and 914 (series), superseded by SI-912-020/SI-914-022, latest edition
SI-26-1994	912 UL	0	0	01.11.1994	TBO for ROTAX engine type 912 UL-series
SI-26-1997	914 UL,912 UL	0	0	01.09.1998	Supplementing the Maintenance Manual in regard to propeller gearbox without overload clutch
SI-27-1994	912 UL	1	0	01.03.1995	Special inspection to increase the TBO for engine type 912 UL
SI-27-1997	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	1	17.07.2012	CANCELLED - Oil level check for ROTAX engine type 912 and 914 (Series), superseded by relevant Maintenance Manual, latest edition
SI-2ST-001	618 UL,582 UL	0	0	01.04.1999	Installation instructions for the new design piston for 582 UL with mono hook piston pin circlip grooves
SI-2ST-002	618 UL,582 UL	0	0	01.05.2000	Change of the exhaust gasket on engine type 582 UL mod. 90/99 und type 618 UL
SI-2ST-004	618 UL,447 UL,582 UL,503 UL	0	1	11.07.2006	Running modifications on ROTAX 2-stroke UL aircraft engines

Document Type	Engine Type	Issue	Revision	Date	Title
SI-2ST-005	582 UL	0	0	01.12.2001	Modified rotary valve cover for ROTAX engine type 582 UL (replaced by SB-2ST-002)
SI-2ST-007	618 UL,582 UL,532 UL,503 UL,447 UL	0	2	20.05.2008	Amendment on reduction gearbox type C and type E for ROTAX 2-stroke UL aircraft engines
SI-2ST-008	618 UL,582 UL,503 UL,447 UL	0	0	08.04.2009	Selection of suitable operating fluids for ROTAX 2-stroke UL engines
SI-3-1995	912 UL,912 A	0	0	01.02.1995	CANCELLED - Cracks in the carburetor flange, engine series type 912, superseded by SB-912-030/SB-914-019 (+UL), latest edition
SI-912-001,SI-914-001	912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	0	01.04.1999	Installation of rotary water pump seal and water pump impeller
SI-912-002,SI-914-004	912 S,912 ULS,912 F,912 A,912 UL,914 F,914 UL	0	0	01.06.1999	Verification of the Lubrication system and replacement of the oil pressure spring for engine type 912 and 914
SI-912-003,SI-914-005	912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	2	19.03.2009	Oil line connections with UNF-threads (AN-8) for ROTAX engine types 912 and 914 (series)
SI-912-004,SI-914-006	912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	0	01.08.1999	CANCELLED - Modified carburetor flange for Rotax engine type 912 (series) and Rotax engine type 914 (series), superseded by SB-912-030/SB-914-019 (+UL), latest edition
SI-912-005,SI-914-007	912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	0	01.02.2000	Lubrication system for all ROTAX engine type 912 (series) and 914 (series)
SI-912-006,SI-914-008	912 S,912 ULSFR,912 ULS,912 F,912 A,912 UL,914 F,914 UL	0	1	03.02.2009	Replacement of the circlip in the sprag clutch housing on ROTAX engine type 912 and 914 (series)
SI-912-007,SI-2ST-003,SI-914-009	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,532 UL,508 UL,503 UL,462 UL,447 UL,377 UL,277 UL,914 UL,914 F	0	0	01.08.2001	Check of the fuel pressure gauge kit part no. 874 230 for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines
SI-912-008	912 S,912 ULSFR,912 ULS,912 F,912 A,912 UL	0	1	01.02.2002	Fuel pressure indication problems on ROTAX engine type 912 (series)
SI-912-009,SI-914-010	912 S,912 ULSFR,912 ULS,912 F,912 A,912 UL,914 F,914 UL	0	0	01.10.2001	Introduction of a new rocker arm bushing for ROTAX engine type 912 and 914 (series)
SI-912-010,SI-912i-005,SI-914-011	912 ULS,912 F,912 UL,912 S,912 A,912 iS,914 UL,914 F	0	-	02.10.2012	Oil change on Rotax engine type 912i, 912 and 914 (Series)
SI-912-011,SI-914-012	912 S,912 ULSFR,912 ULS,912 F,912 A,912 UL,914 F,914 UL	0	0	01.03.2003	Replacement of the gasket rings on the adaptor of the oil radiator for Rotax engine type 912 and 914 (series)
SI-912-012,SI-914-014	912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	1	01.03.2004	Routine Modifications of the Bing constant depression carburetor on ROTAX engine type 912 and 914 (Series)
SI-912-013,SI-914-016	912 ULS,912 S,912 ULSFR,912 F,912 A,912 UL,914 F,914 UL	0	0	01.04.2004	Standardization of the ignition unit for ROTAX engine type 912 and 914 (Series)
SI-912-014,SI-914-017	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,914 UL,914 F	0	0	01.06.2004	Optimizing of piston ring position for ROTAX engine type 912 and 914 (Series)
SI-912-015,SI-914-018	912 S,912 ULSFR,912 ULS,912 F,912 A,912 UL,914 F,914 UL	0	0	01.06.2004	Increase of disk spring pre-tension in the gearbox on ROTAX engine type 912 and 914 (Series)

Document Type	Engine Type	Issue	Revision	Date	Title
SI-912-016,SI-912i-001,SI-914-019	912 UL,912 S,912 F,912 A,912 ULSFR,912 ULS,912 iSc SPORT,912 iS SPORT,912 iS,914 UL,914 F	0	-	16.04.2015	Selection of suitable operating fluids for Rotax engine type 912 i, 912 and 914 (Series)
SI-912-017,SI-2ST-006	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,503 UL,447 UL	0	0	22.12.2006	Airfilter for Rotax engine type 912 (Series) and 2-stroke UL aircraft engines
SI-912-018,SI-912i-004,SI-914-020	912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,912 iS,914 UL,914 F	0	-	02.10.2012	Purging of lubrication system for Rotax engine type 912i, 912 and 914 (Series)
SI-912-019,SI-912i-006,SI-914-021	912 ULS,912 S,912 ULSFR,912 F,912 A,912 UL,912 iSc SPORT,912 iS SPORT,912 iS,914 UL,914 F	0	-	13.06.2014	Oil leakages in the area of the cylinder barrel for Rotax engine type 912i, 912 and 914 (Series)
SI-912-020,SI-914-022	912 S,912 A,914 F,912 F,912 UL,914 UL,912 ULS	0	9	30.12.2016	Running Modifications on ROTAX Engine Type 912/914 (Series)
SI-912-021,SI-914-023,SI-2ST-009	912 F,912 A,914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,535 B,503 UL,618 UL,505 A,505,535 A,277 UL,535 C,582 UL,447 UL	0	0	09.11.2009	Inspection of carburetors for ROTAX engine type 912 and 914 (Series) and 2-stroke UL aircraft engines
SI-912-022	912 ULSFR,912 ULS,912 S,912 F,912 A,912 UL	0	0	20.01.2014	Cancelation of the 5-years change interval for fuel hoses (teflon hoses) for ROTAX Engine Type 912 (Series)
SI-912-025,SI-914-026,SI-912i-010	912 F,914 UL,912 S,912 iSc SPORT,912 ULS,914 F,912 A,912 iS,912 UL,912 iS SPORT	0	0	30.12.2016	Change of Tightening Torque Procedure for the Installation of Cylinder Heads on ROTAX Engine Type 912 i, 912 and 914 Series
SI-912i-002	912 iSc SPORT,912 iS SPORT,912 iS	0	1	13.06.2014	B.U.D.S. Aircraft Installation Instructions for ROTAX Engine Type 912 i Series
SI-912i-003	912 iSc SPORT,912 iS SPORT,912 iS	0	4	13.06.2014	B.U.D.S. Aircraft Update for ROTAX Engine Type 912 i Series
SI-912i-007,SI-914-024,SI-912-023	912 iSc SPORT,912 iS SPORT,912 iS,914 F,912 S,912 F,912 A	0	0	04.11.2015	Introduction of a radiator retrofit kit part no. 881535 for the new radiator part no. 997083 on ROTAX engine type 912i, 912 and 914 (Series)
SI-912i-008,SI-914-025,SI-912-024	912 iSc SPORT,912 iS SPORT,912 iS,914 F,912 S,912 F,912 A	0	0	19.11.2015	Introduction of new oil radiator/-sets on ROTAX Engine Type 912 i, 912 und 914 (Series)
SI-912i-009	912 iSc SPORT,912 iS SPORT,912 iS	0	0	21.01.2016	Introduction of a new fuel filter part no. 874060 for ROTAX Engine Type 912 iS and 912 iS Sport
SI-914-002	914 F,914 UL	0	0	01.04.1999	Optimizing of mixture distribution
SI-914-003	914 UL,914 F	0	1	15.04.2008	Inspection and lubrication of Wastegate for ROTAX engine type 914 (Series)
SI-914-013	914 F,914 UL	0	0	01.04.2003	Introduction of a new airbox for Rotax engine type 914 (series)
SI-914-015	914 F,914 UL	0	0	01.12.2003	Introduction of a new airbox part no. 667167 for Rotax engine type 914 (Series)

Document Type	Engine Type	Issue	Revision	Date	Title
SL-2ST-002	447 UL,377 UL,277 UL,582 UL,535 C,535 B,535 A,532 UL,505 A,505,618 UL,503 UL,501,462 UL	0	1	12.01.2005	Documentations for ROTAX 2-stroke UL engines and certified 2-stroke aircraft engines
SL-2ST-005	503 UL,618 UL,582 UL,447 UL	0	0	01.07.2001	Running modifications on carburetors for ROTAX 2-stroke UL aircraft engines
SL-912-007	912 ULSFR	0	1	15.03.2011	ROTAX engine type 912 ULSFR - version for France
SL-912-008	912 ULS,912 UL,912 S,912 F,912 A	0	0	20.07.2000	CANCELLED - Operators and Maintenance Manual for ROTAX 912 Series - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition
SL-912-010	912 ULSFR,912 ULS,912 S	0	0	01.02.2003	Identifying abnormal vibrations on aircrafts equipped with Rotax engine type 912 S/ULS/ULSFR
SL-912-016,SL-914-014	912 A,912 F,914 F,912 ULS,912 S,914 UL,912 UL	0	1	30.12.2016	Essential information regarding engine behavior, performance and manifold pressure data for ROTAX Engine Type 912 and 914 (Series)
SL-912i-003	912 iSc SPORT,912 iS SPORT,912 iS	0	2	07.07.2016	Warranty conditions for ROTAX Engine Type 912 i Series
SL-914-001,SL-2ST-001,SL-912-001	914 UL,914 F,447 UL,377 UL,277 UL,582 UL,535 C,535 B,535 A,532 UL,508 UL,505 A,505,912 ULS,912 UL,912 S,912 F,912 A,618 UL,503 UL,501,463,462 UL	0	1	01.07.1999	Change of desig. of Tech. Bulletins and Service Information in acc. with the new ROTAX standard for ROTAX 2-stroke UL aircraft engines, ROTAX 912 (series) and ROTAX 914 (series)
SL-914-002,SL-912-002	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	2	28.05.2010	Standardization of the crankshaft/piston pin and of the gearbox for ROTAX engine type 912/914 (Series)
SL-914-003,SL-2ST-003,SL-912-003	914 UL,914 F,447 UL,377 UL,277 UL,275,185,582 UL,532 UL,535 C,535 B,535 A,912 ULS,912 UL,912 S,912 F,912 A,508 UL,505 A,505,503 UL,618 UL,501,463,462 UL	0	2	01.07.2000	CANCELLED - List of documentation for ROTAX 2-Stroke Aircraft engines and all versions of engine Type 912 / 914 - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition
SL-914-004,SL-912-004	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A	0	2	15.04.2008	Documentation for ROTAX engine type 912 and 914 (Series)
SL-914-005,SL-912-005,SL-2ST-004	914 UL,914 F,912 ULS,912 UL,912 S,912 F,912 A,377 UL,582 UL,535 C,535 B,535 A,532 UL,505 A,505,503 UL,618 UL,501,462 UL,447 UL	0	0	01.12.1999	Change of layout for: Alert Service Bulletin (ASB), Service Bulletins (SB), Service Instructions (SI) and Service Letters (SL)
SL-914-006,SL-912-006,SL-912i-006	914 UL,914 F,912 ULS,912 UL,912 S,912 iSc SPORT,912 iS SPORT,912 iS,912 F,912 A	0	-	23.07.2014	Use of third party after-market piston kits in Rotax engines type 912 (series) and 914 (series)
SL-914-007	914 UL,914 F	0	0	01.07.2000	CANCELLED - Operators and Maintenance Manual for ROTAX 914 Series - superseded by SB-2ST-000/SB-912-000/SB-914-000, current edition
SL-914-008,SL-912-009	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A	0	1	01.12.2003	CANCELLED - Coolant for ROTAX engine type 912 and 914 (Series), superseded by SB-912-043/SB-914-029, latest edition

Document Type	Engine Type	Issue	Revision	Date	Title
SL-914-009,SL-912-011,SL-912i-002	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,912 iS	0	-	02.10.2012	Use of an oil thermostat for Rotax engine type 912i, 912 and 914 (Series)
SL-914-010,SL-912-012,SL-2ST-006	914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,582 UL,914 UL,503 UL,447 UL	0	3	07.07.2016	Warranty conditions for ROTAX engine types 912 and 914 (Series) and 2-stroke aircraft engines
SL-914-011,SL-912-013,SL-2ST-007	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,618 UL,582 UL,505,503 UL,463,462 UL,447 UL,377 UL	0	10	24.02.2017	List of stolen ROTAX engines type 912 and 914 (Series) and 2-stroke aircraft engines
SL-914-012,SL-912-014,SL-912i-005,SL-2ST-008	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,912 iSc SPORT,912 iS SPORT,912 iS,618 UL,535 C,503 UL,505,447 UL,505 A,535 B,277 UL,535 A,582 UL	0	-	01.09.2014	Non-approved modifications or use of ROTAX unapproved engine components or accessories for ROTAX aircraft engines
SL-914-013,SL-912-015,SL-2ST-009,SL-912i-001	914 UL,914 F,912 ULSFR,912 ULS,912 UL,912 S,912 F,912 A,447 UL,582 UL,912 iS,618 UL,503 UL,535 C,535 B,535 A,505,912 iSc SPORT,912 iS SPORT,505 A	0	-	08.03.2012	Definition for propeller strike or accidental engine stoppage on ROTAX engine type 912 i, 912 and 914 (Series) and 2-stroke aircraft engines
SL-914-015,SL-912-017,SL-912i-004	914 UL,912 ULS,912 UL,912 S,912 F,912 A,912 iS,914 F,912 ULSFR	0	1	07.07.2016	Conditions relating to the Limited Extended Warranty for ROTAX Engine Types 912/914 Series and 912 i Series
SL-914-016,SL-2ST-010,SL-912-018,SL-912i-007	914 UL,535 A,503 UL,912 S,535 C,277 UL,505 A,912 iS,912 F,535 B,618 UL,505,912 iS SPORT,912 A,447 UL,914 F,582 UL	0	0	08.09.2016	Language Standardization in Technical Documentation for ROTAX® Aircraft Engines