

SERVICE BULLETIN

EMPLOYMENT OF A MUFFLER OF REDUCED NOISE EMISSION FOR ROTAX_® ENGINE TYPE 914UL (SERIES) SB-914-006UL

OPTIONAL

Repeating symbols:

Please, pay attention to the following symbols throughout this document emphasizing particular information.

▲ WARNING: Identifies an instruction, which if not followed, may cause serious injury or even death.

■ CAUTION: Denotes an instruction which if not followed, may severely damage the engine or could lead to

suspension of warranty.

◆ NOTE: Information useful for better handling.

1) Planning information

1.1) Engines affected

All versions of the engine type:

- 914 UL (Series) from S/N 4,417.501 to S/N 4,418.268

- V914 pre-production

if they are equipped with the genuine $ROTAX_{\odot}$ muffler part no. 979402. In modification of this art contact your aircraft builder. On engines with S/N higher than those listed above the muffler (part no. 979402) was already fitted in serial production.

For complete instructions and compliance to this service bulletin refer to Service Bulletin SB-914-006, latest edition section 1.2 onward.

♦ NOTE: Section 1.6) Approval: Is not required for engines of the type UL (series).

Section 3) Accomplishment: In addition:persons with adequate type-specific training.